



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

Errata Notification

EN #: LEN-02-01

Errata Revision #: 0

Issue Date: May 3, 2002

Effective Date: May 3, 2002

Product Affected: IDTQS32X384, IDTQS32XL384, IDTQS32X2384, IDTQS32XVH384

ERRATA DETAILS:

ATTACHMENT

☐ Yes

☒ No

- ☒ Data Sheet Errata
- ☐ Device Errata
- ☐ Device Manual Errata
- ☐ Application Notes Errata
- ☐ Other (Please Specify)

Pin names on the datasheets were swapped as follows:

<u>Pin #</u>	<u>Was (In-correct)</u>	<u>Is (Correct)</u>
34	B14	A14
35	A14	B14

IDT Web Site Location:

http://www.idt.com/products/pages/Bus_Switches.html

CUSTOMER NOTIFICATION:

As a result of Errata listed above, IDT has decided to notify you through this Errata Notification.
We recommend you to review this notification in details prior to the use of affected product in your application.
Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____

E-Mail Address: _____

Name/Date: _____

Phone #: _____

Title: _____

Fax #: _____

CUSTOMER COMMENTS:
