

RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RX*-A191A/E	Rev.	1.00
Title	Errata to RX Family User's Manuals Regarding the External Bus		Information Category	Technical Notification		
Applicable Product	RX64M Group, RX71M Group, RX65N Group, RX651 Group	Lot No.	Reference Document	User's Manual: Hardware for applicable products (see the table at the last page)		
		All				

This document describes correction to the section of the Buses in User's Manual: Hardware for the applicable products.

Page and section numbers are based on the RX64M Group. Refer to the table on the last page for the corresponding page and section numbers in the other groups.

Errata

The value after reset of the CSnCR.BSIZE[1:0] bits in section 16.3.1 is corrected as follows (n = 1 to 7).

•Page 488 of 2936

Before correction

Address(es): CS1CR 0008 3812h, CS2CR 0008 3822h, CS3CR 0008 3832h,
CS4CR 0008 3842h, CS5CR 0008 3852h, CS6CR 0008 3862h, CS7CR 0008 3872h

b15	b14	b13	b12	b11	b10	b9	b8	b7	b6	b5	b4	b3	b2	b1	b0
—	—	—	MPXEN	—	—	—	EMOD E	—	—	BSIZE[1:0]	—	—	—	—	EXENB

Value after reset: 0 0 0 0 0 0 0 0 0 0 1 0 0 0 0 0

After correction

Address(es): CS1CR 0008 3812h, CS2CR 0008 3822h, CS3CR 0008 3832h,
CS4CR 0008 3842h, CS5CR 0008 3852h, CS6CR 0008 3862h, CS7CR 0008 3872h

b15	b14	b13	b12	b11	b10	b9	b8	b7	b6	b5	b4	b3	b2	b1	b0
—	—	—	MPXEN	—	—	—	EMOD E	—	—	BSIZE[1:0]	—	—	—	—	EXENB

Value after reset: 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

Reference Documents

Applicable Product	Related Document	Page Number	Chapter Number
RX64M Group	RX64M Group User's Manual: Hardware Rev.1.10 (R01UH0377EJ0110)	Page 488 of 2936	16.3.1
RX65N Group, RX651 Group	RX65N Group, RX651 Group User's Manual: Hardware Rev.2.10 (R01UH0590EJ0210)	Page 495 of 2695	16.3.1
RX71M Group	RX71M Group User's Manual: Hardware Rev.1.10 (R01UH0493EJ0110)	Page 495 of 2952	16.3.1

End of document