Date: Nov. 26, 2012

RENESAS TECHNICAL UPDATE

1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RX*-A036A/E	Rev.	1.00
Title	Note on Setting Clock for Realtime Clock (RTC) of RX210 Group		Information Category	Technical Notification		
		Lot No.		RX210 Group User's Manual: Hardware Rev.1.10 (R01UH0037EJ0110)		
Applicable Product	RX210 Group	All	Reference Document			

1	Ν	loi	te

When the frequency of the peripheral module clock (PCLK) is lower than the frequency of the RTC count source, registers associated with the RTC may not be accessed properly.

2. Measure

Set the PCLK frequency to satisfy the following condition:

PCLK frequency ≥ frequency of the RTC count source