

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development Environment		No	TN-EML-107A/E	Rev	1
THEME	Problems with the SH7290,SH7705,SH7630,SH7294,SH7300Series E10A Emulators	Classification of Information		1. Spec change 2. Supplement of Documents ③ Limitation of Use 4. Change of Mask 5. Change of Production Line		
PRODUCT NAME	SH7290,SH7705,SH7630,SH7294,SH7300Series E10A Emulator	Lot No.	Reference Documents	SH7290 E10A Emulator User's Manual Rev1.0 ADE-702-289, SH7705 E10A Emulator User's Manual Rev1.0 ADE-702-317, SH7630 E10A Emulator User's Manual Rev1.0 ADE-702-318, SH7294 E10A Emulator User's Manual Rev1.0 ADE-702-346, SH7300Series E10A Emulator User's Manual Rev1.0 ADE-702-363		Effective Date
		V1.00				Eternity

We have found that SH7290,SH7705,SH7630,SH7294,SH7300Series E10A emulators have the following problems:

TLB Error' is displayed when a verification error is caused by the Fill command.

Note that the operation is performed normally although these messages are incorrect.
These problems are to be corrected in V2.0.00.