

RENESAS TOOL NEWS on Sep. 1, 2008: 080901/tn9

## Corrections to the User's Manuals of the User System Interface Boards for the E200F Emulator R0E0200F1EMU00

We notify corrections to the user's manuals of the user system interface boards for the E200F Emulator R0E0200F1EMU00. The emulator and the boards are used for the SuperH RISC engine family of MCUs.

---

### 1. Corrections

Two dimensional errors have been found in each of the illustrations of the user system interface boards shown at the bottom of the pages listed in 2 below; that is, at the bottom left of each illustration, read 5.81 for 5.0 that is written in the vertical orientation, and read 5.5 for 5.0 written in the horizontal orientation. Refer to here for these corrections.

### 2. Documents and Pages Concerned

- (1) Page 14, Figure 7 in "SH7083 Group PTQP0100KA-A User System Interface Board [R0E570830CFK00] User's Manual" REV.4.00 (Document No. REJ10J1203-0400)
- (2) Page 17, Figure 7 in "SH7084 Group PLQP0112JA-A User System Interface Board [R0E570840CFJ00] User's Manual" REV.4.00 (Document No. REJ10J1204-0400)
- (3) Page 16, Figure 7 in "SH7085 Group PLQP0144KA-A User System Interface Board [R0E570850CFK00] User's Manual" REV.4.00 (Document No. REJ10J1205-0400)
- (4) Page 16, Figure 7 in "SH7086 Group PLQP0176KB-A User System Interface Board [R0E570860CFK00] User's Manual" REV.4.00 (Document No. REJ10J1206-0400))
- (5) Page 11, Figure 5 in "SH7124 Group PLQP0048JA-A User System Interface Board [R0E571240CFJ00] User's Manual" REV.2.00 (Document No. REJ10J1207-0200)

- (6) Page 11, Figure 5 in "SH7125 Group PRQP0064GB-A User System Interface Board [R0E571250CFG00] User's Manual" REV.3.00  
(Document No. REJ10J1208-0300)
- (7) Page 11, Figure 5 in "SH7125 Group PLQP0064KB-A User System Interface Board [R0E571250CFK00] User's Manual" REV.2.00  
(Document No. REJ10J1209-0200)
- (8) Page 11, Figure 5 in "SH7146 Group PLQP0080JA-A User System Interface Board [R0E571460CFJ00] User's Manual" REV.4.00  
(Document No. REJ10J1210-0400)
- (9) Page 14, Figure 7 in "SH7147 Group PLQP0100KB-A User System Interface Board [R0E571470CFK00] User's Manual" REV.5.00  
(Document No. REJ10J1211-0500)
- (10) Page 14, Figure 7 in "SH7149 Group PRQP0100JE-B User System Interface Board [R0E571490CFJ00] User's Manual" REV.3.00  
(Document No. REJ10J1212-0300)
- (11) Page 14, Figure 7 in "SH7149 Group PLQP0100KB-A User System Interface Board [R0E571490CFK00] User's Manual" REV.5.00  
(Document No. REJ10J1213-0500)
- (12) Page 10, Figure 5 in "SH7136 Group PLQP0080JA-A User System Interface Board [R0E571360CFJ00] User's Manual" REV.1.00  
(Document No. REJ10J1774-0100)
- (13) Page 13, Figure 7 in "SH7137 Group PLQP0100KB-A User System Interface Board [R0E571370CFK00] User's Manual" REV.1.00  
(Document No. REJ10J1775-0100)
- (14) Page 12, Figure 5 in "SH7243 Group PLQP0100KB-A User System Interface Board [R0E572430CFK00] User's Manual" REV.1.00  
(Document No. REJ10J1665-0100)
- (15) Page 12, Figure 5 in "SH7285 Group PLQP0144KA-A User System Interface Board [R0E572850CFK00] User's Manual" REV.1.00  
(Document No. REJ10J1664-0100)
- (16) Page 11, Figure 5 in "SH7286 Group PLQP0176KB-A User System Interface Board [R0E572860CFK00] User's Manual" REV.1.00  
(Document No. REJ10J1776-0100)
- (17) Page 12, Figure 5 in "SH7286 Group PLQP0176LB-A User System Interface Board [R0E572860CFL00] User's Manual" REV.1.00  
(Document No. REJ10J1777-0100)
- (18) Page 11, Figure 5 in "SH7211 Group FP-144L User System Interface Board [R0E572110CFK00] User's Manual" REV.1.01  
(Document No. REJ10J1317-0101)
- (19) Page 11, Figure 5 in "SH7206 Group FP-176C User System Interface Board [R0E572060CFK00] User's Manual" REV.1.02  
(Document No. REJ10B0179-0102)

---

**[Disclaimer]**

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.