

RENESAS TOOL NEWS on May 16, 2014: 140516/tn1

Note on Using Integrated Development Environment CubeSuite+ for RX Family V2.02.00

When using the CubeSuite+ for the RX Family V2.02.00, take note of the following problem:

- With debugging the RX220 group
-

1. Products Concerned

- C/C++ Compiler and IDE for RX Family
- Evaluation edition of CubeSuite+

This problem applies for either of the above products with CubeSuite+ common program V2.02.00.

To check to see your version number, refer to the following URL:
https://www.renesas.com/cs+_ver

2. MCUs Involved

In the RX220 group: R5F52201BxFK, R5F52201BxFL, and R5F52201BxFM

3. Descriptions

3.1 In the case of creating a new project for the target microcontroller using CubeSuite+ V2.02.00

Even though "RX E1(Serial)(L)" or "RX E20(Serial)(R)" is selected as the debug tool, connection to the debug tool will not succeed and CubeSuite+ will still not operate correctly after this.

3.2 In the case of loading a project for the target microcontroller that was created using a CubeSuite+ whose version is earlier than V2.02.00

When loading a project for which "RX E1(Serial)(L)" or "RX E20(Serial)(R)" is selected as the debug tool, the following error message is displayed and the project file cannot be opened.

Error(E0202002)

Opening a project failed.

[Direct Error Cause]

Enter a value in the range of 0 to FC00.(W0603018)

4. Workarounds

4.1 In the case of creating a new project for the target microcontroller

For the microcontroller to be used, select a microcontroller in the RX220 group other than the target microcontroller.

Note that though the on-chip ROM size and on-chip RAM size are increased compared to the target microcontroller, this does not cause a problem in debugging as long as the increased memory areas are not used.

For example, if R5F52203BxFK, R5F52203BxFL, or R5F52203BxFM is selected, the on-chip ROM size is increased by 32 KB (0xFFFF0000-0xFFFF7FFF) and the on-chip RAM size by 4 KB (0x00001000-0x00001FFF) compared to the target microcontroller. These increased areas should not be used.

4.2 In the case of using a project that was created using a CubeSuite+ whose version is earlier than V2.02.00

Please consult your local Renesas Electronics marketing office or distributor.

5. Schedule for Fixing the Problem

This problem will be fixed in the next version of the CubeSuite+ common program.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.