

RENESAS TOOL NEWS on December 1, 2014: 141201/tn5

Device Information (Managed by CS+) for RL78 Family Revised to V3.00.01

We will be revising the device information file (managed by CS+) for the RL78 family of MCUs and accordingly will change the version number from 3.00.00 to 3.00.01.

- 1. Product and Versions to Be Updated
 - (1) Device information file managed by CubeSuite+ for the RL78 family of MCUs (CubeSuite+ DevInfo_RL78_78K)
 V1.00.18 or earlier
 - (2) Device information file managed by CS+ for the RL78 family of MCUs (CS+ for CA,CX Device Information for RL78) V3.00.00

Check your version number of "CubeSuite+ DevInfo_RL78_78K" or "CS+ for CA,CX Device Information for RL78" with reference to the procedure described under the heading "Components" at the URL below. https://www.renesas.com/cs+_ver

- 2. Description of Revision
 - (1) Correction to Pin Assignment Information

 The pin assignment information for the following MCUs will be corrected.
 - RL78 family, RL78/F13 group
 - RL78 family, RL78/F14 group
 - (2) Correction to Debugging Information

 The debugging information related to the MCUs below will be corrected.
 - RL78 family RL78/G1G group

For more information, refer to the URL below (the information will be on the page from December 5).

https://www.renesas.com/cubesuite+/CSP_DevInfo_RL78.html

3. Updating Your Product

Online updating is available free of charge. To update either your commercial edition or evaluation edition of CS+, use either of the following methods.

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

(1) On the Start menu, select Programs and then Renesas Electronics CS+ to start the Update Manager.

This service will be available from December 5.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

Installation is suspended because "CubeSuite+W.exe" is running.

It will be resumed next time you start the tool.

(2) Download and install V3.00.01 of device information file managed by CS+ for the RL78 family of MCUs from the following URL.

https://www.renesas.com/cs+_download

The above program will be available from December 5.

3.2 For CubeSuite+ V2.02.01 or Earlier

Please download and install the evaluation edition of CS+ V3.00.00 from the following URL:

https://www.renesas.com/cs+_download

Then, update your program by using the method in 3.1 (1) or (2) above.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.