

## Supplemental Information

This notice describes the differences between the updated version (Version 4, dated December 4, 2006) and its previous version (Version 3, dated April 7, 2006) of the IDT82V2608 data sheet. It helps readers to identify the changes when the data sheet is upgraded.

## Revision History

Revision Date	PCN Number (if applicable)	Date Code	Changed Items
December 4, 2006	-	-	11
April 7, 2006	-	-	3-10
December 8, 2003	-	-	1-2

## Changed Items

### December 4, 2006

**Item 11:** Changed the unit of the  $T_{in}$  and  $T_{exit}$  parameters in the 'ConfigDev Command' from '250 ms' to '1 s' (Page 33)

### April 7, 2006

**Item 10:** Changed the identification code from '004B8067' to '104B8067' (Page 80)

**Item 9:** Changed attributes for LODS (Page 72)

**Item 8:** Changed GetLinkWorkingPara Command (Encoding: 1EH) description (Page 65)

**Item 7:** Changed ConfigGSMTimers Command (Encoding: 08H) description (Page 41)

**Item 6:** Changed FIFO Interrupt Reset Register (06H) description (Page 26)

**Item 5:** Changed the default value for FIFO Interrupt Status Register (05H) (Page 26)

**Item 4:** Added HW version bits to FIFO Interrupt Status Register (05H) (Page 26)

**Item 3:** Deleted "Supports line side clock detection" in the feature list. (Page 9)

### December 8, 2003

**Item 2:** Changed datasheet status from "Advance" to "Final"

**Item 1:** Changed IMAOS version