

Supplemental Information

This Document Errata reflects changes required for the following device datasheet below.

8N3QV01KC-0017CDI	83PN187DKILF	813N252AKI-04LF
8N3PGDAMBKI-025LF	83PN161AKILF	813N252AKI-02LF
849N2505AKILF	83PN156DKILF	813N252AK-02LF
843N252GG-45LF	83PN148DKILF	8N3QV01ACJI-01
841N4830AKILF	813N2532AKLF	8N3QV01LCJI-034
841N4830AKI-09LF	813N2532AKILF	8N3Q001FCJI-001
83PN625DKILF	813N252AKI-09LF	

Revision History

April 15, 2011: First version of documentation errata for the affected device.

Errata Item

CURRENT: Absolute Maximum Ratings

Product	Supply Voltage, V_{DD}	Product	Supply Voltage, V_{DD}
8N3QV01KC-0017CDI	4.5V	83PN148DKILF	4.5V
8N3PGDAMBKI-025LF	4.6V	813N2532AKLF	4.5V
849N2505AKILF	4.6V	813N2532AKILF	4.5V
843N252GG-45LF	4.6V	813N252AKI-09LF	4.6V
841N4830AKILF	4.5V	813N252AKI-04LF	4.6V
841N4830AKI-09LF	4.5V	813N252AKI-02LF	4.6V
83PN625DKILF	4.6V	813N252AK-02LF	4.6V
83PN187DKILF	4.5V	8N3QV01ACJI-011	4.5V
83PN161AKILF	4.5V	8N3QV01LCJI-034	4.5V
83PN156DKILF	4.6V	8N3Q001FCJI-001	4.5V

CHANGE TO: Absolute Maximum Ratings

Supply Voltage, V_{DD} = 3.63V