



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: L-03-04

Last Buy Date: October 24, 2003

Issue Date: July 28, 2003

Last Ship Date: January 23, 2004

PRODUCT(S) AFFECTED:
(List Replacement Part #(s), if any)

ATTACHMENT ☒ Yes ☐ No

Please see attachment for affected part numbers.

REASON FOR DISCONTINUANCE:

- ☐ Replace slower speed with faster speed offerings ☐ Other:
☐ Obsolete Fab Technology / Process
☐ Obsolete Assembly Technology / Process
☐ Obsolete Package / Material
☒ Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____

E-Mail Address: _____

Name/Date: _____

Phone#: _____

Title: _____

Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____

Date: _____



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment: PDN # L-03-04

Affected IDT Part#	Replacement Part#
IDT74ALVC162334PV	No Replacement
IDT74ALVC162344PA	No Replacement
IDT74ALVC162344PF	No Replacement
IDT74ALVC162344PV	No Replacement
IDT74ALVC162835PV	No Replacement
IDT74ALVC162836PF	No Replacement
IDT74ALVC16835PV	No Replacement
IDT74ALVC16841PF	No Replacement
IDT74ALVC16841PV	No Replacement
IDT74ALVC245Q	No Replacement
IDT74ALVC245PY	No Replacement
IDT74ALVCF162835APV	No Replacement
IDT74ALVCH162268PV	No Replacement
IDT74ALVCH162373PF	No Replacement
IDT74ALVCH16260PF	No Replacement
IDT74ALVCH162721PF	No Replacement
IDT74ALVCH162721PV	No Replacement
IDT74ALVCH16276PF	No Replacement
IDT74ALVCH162820PF	No Replacement
IDT74ALVCH162820PV	No Replacement
IDT74ALVCH16345PF	No Replacement
IDT74ALVCH16345PV	No Replacement
IDT74ALVCH16373PF	No Replacement
IDT74ALVCH16501PF	No Replacement
IDT74ALVCH16601PF	No Replacement
IDT74ALVCH16646PF	No Replacement
IDT74ALVCH16652PF	No Replacement
IDT74ALVCH16652PV	No Replacement
IDT74ALVCH16721PF	No Replacement
IDT74ALVCH16823PF	No Replacement
IDT74ALVCH16823PV	No Replacement
IDT74ALVCH16836PF	No Replacement
IDT74ALVCH16836PV	No Replacement

Affected IDT Part#	Replacement Part#
IDT74ALVCH16863PF	No Replacement
IDT74ALVCH16863PV	No Replacement
IDT74ALVCH16903PF	No Replacement
IDT74ALVCHR162269APF	No Replacement
IDT74ALVCHR16501PF	No Replacement
IDT74ALVCHR16501PV	No Replacement
IDT74ALVCHR16601PF	No Replacement
IDT74ALVCHR16601PV	No Replacement
IDT74FCT162500ATPA	No Replacement
IDT74FCT162500CTPA	No Replacement
IDT74FCT162601ATPA	No Replacement
IDT74FCT162601CTPA	No Replacement
IDT74FCT162601ATPV	No Replacement
IDT74FCT162601CTPV	No Replacement
IDT74FCT162701TPA	No Replacement
IDT74FCT162701ATPA	No Replacement
IDT74FCT163344APF	No Replacement
IDT74FCT163344CPF	No Replacement
IDT74FCT163601APV	No Replacement
IDT74FCT16601ATPV	No Replacement
IDT74FCT16601CTPV	No Replacement
IDT74FCT2373ATPG	No Replacement
IDT74FCT2373CTPG	No Replacement
IDT74FCT2374ATPG	No Replacement
IDT74FCT2374CTPG	No Replacement
IDT74FCT2573ATPG	No Replacement
IDT74FCT2573CTPG	No Replacement
IDT74FCT2574ATPG	No Replacement
IDT74FCT2574CTPG	No Replacement
IDT74FCT2827ATPG	No Replacement
IDT74FCT2827CTPG	No Replacement
IDT74FCT377ATPY	No Replacement
IDT74FCT377CTPY	No Replacement



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment: PDN # L-03-04

Affected IDT Part#	Replacement Part#
IDT74FCT377DTPY	No Replacement
IDT74FCT648ATQ	No Replacement
IDT74FCT648CTQ	No Replacement
IDT74FCT652ATPY	No Replacement
IDT74FCT652CTPY	No Replacement
IDT74FST163211PV	No Replacement
IDT74FST163P245PV	No Replacement
IDT74FST32XL2384PV	No Replacement
IDT74FST6800SO	No Replacement
IDT74LVC112AQ	No Replacement
IDT74LVC112ADC	No Replacement
IDT74LVC112APY	No Replacement
IDT74LVC16344APF	No Replacement
IDT74LVC163ADC	No Replacement
IDT74LVC163AQ	No Replacement
IDT74LVC163APY	No Replacement
IDT74LVC16501APF	No Replacement
IDT74LVC16601APF	No Replacement
IDT74LVC16646APF	No Replacement
IDT74LVC16827APF	No Replacement
IDT74LVC823ASO	No Replacement
IDT74LVCC4245ASO	No Replacement
IDT74LVCH162373APF	No Replacement
IDT74LVCH162374APF	No Replacement
IDT74LVCH162721APV	No Replacement
IDT74LVCH16276APF	No Replacement
IDT74LVCH162823APV	No Replacement
IDT74LVCH16373APF	No Replacement
IDT74LVCH16501APF	No Replacement
IDT74LVCH16543APF	No Replacement
IDT74LVCH16652APF	No Replacement
IDT74LVCH16827APF	No Replacement

Affected IDT Part#	Replacement Part#
IDT74LVCH2244ASO	No Replacement
IDT74LVCH2244APY	No Replacement
IDT74LVCH2245APY	No Replacement
IDT74LVCHR16501APF	No Replacement
IDT74LVCHR16952APA	No Replacement
IDT74LVCHR16952APF	No Replacement
IDT74LVCHR16952APV	No Replacement
IDT74LVCR16952APF	No Replacement
IDT74LVCR16952APV	No Replacement
IDTQS32257SO	No Replacement
IDTQS3800PA	No Replacement
IDTQS3800SO	No Replacement
IDTQS3L383SO	No Replacement
IDTQS3R384SO	No Replacement
IDTQS3VH126PA	No Replacement
IDTQS74FCT158ATSO	No Replacement
IDTQS74FCT158CTSO	No Replacement
IDTQS74FCT158ATS1	No Replacement
IDTQS74FCT158CTS1	No Replacement
IDTQS74FCT2374TQ	No Replacement
IDTQS74FCT2374ATQ	No Replacement
IDTQS74FCT2374CTQ	No Replacement
IDTQS74FCT2541TSO	No Replacement
IDTQS74FCT2541ATSO	No Replacement
IDTQS74FCT2541CTSO	No Replacement
IDTQS74FCT2573TSO	No Replacement
IDTQS74FCT2573ATSO	No Replacement
IDTQS74FCT2574TSO	No Replacement
IDTQS74FCT2574ATSO	No Replacement
IDTQS74FCT2574CTSO	No Replacement
IDTQS74FCT2823ATSO	No Replacement
IDTQS74FCT2823BTSO	No Replacement