

STANDARD LIFE CYCLE OF COMPILERS

NOVEMBER 13, 2019

R20UT4659EJ0100

Rev. 1.00


SOFTWARE PLANNING AND SUPPORT DEPARTMENT

SOFTWARE DEVELOPMENT DIVISION

IOT AND INFRASTRUCTURE BUSINESS UNIT

RENESAS ELECTRONICS CORPORATION

STANDARD LIFE CYCLE OF COMPILERS




End of the general support service for $V_m.0 \sim n$

Service contents	Time of the service discontinuation
Technical support (from Web) - information service (tool news)	Whichever lasts long: one year after the end of sales of $V_m.n$ (last revision) or 5 years after $V_m.n$ is released
Bug fix	One year after the end of sales of $V_m.n$ (when incorrect codes are output and there is no workarounds)

- You can continuously use the compiler even if the general support service discontinued.
- Please make a contract of [Compiler Maintenance Service \(pay service\)](#) if you need service.

STANDARD LIFE CYCLE OF COMPILERS

CASE OF RH850 COMPILER CC-RH




End of the general support service for V1.00.00~V1.07.00

Service contents	Time of the service discontinuation
Technical support (from Web) - information service (tool news)	5 years after V1.07 is released (2023/1)
Bug fix	One year after the end of sales of V1.07 (2019/7)

STANDARD LIFE CYCLE OF COMPILERS

CASE OF RX COMPILER CC-RX



End of the general support service for V2.00.00~V2.08.00

Service contents	Time of the service discontinuation
Technical support (from Web) - information service (tool news)	5 years after V2.08 is released (2023/1)
Bug fix	One year after the end of sales of V2.08 (2019/11)

Revision history

Doc NO.	Issue date	Description	
		Page	Summary
R20UT4659 EJ0100	November 13, 2019	—	First Edition issued

[Renesas.com](https://www.renesas.com)