

PRODUCT ADVISORY

**Part Marking Configuration Change for
Intersil Product IS9-705RH*
(DSCC 5962R0053801*XC)**

**Refer to:
PA10040**

Date: April 16, 2010


April 16, 2010

To: Our Valued Intersil Customers

Subject: Part Marking Configuration Change for Intersil Product IS9-705RH-*
(DSCC 5962R0053801*XC)

This advisory is to inform you that Intersil is changing the configuration of the “top side” marking (brand) for the listed IS9-705RH* (DSCC 5962R0053801*XC) products. The marking layout is being restructured to utilize a 4-digit date code (2-digit year plus 2-digit week) instead of the current 3-digit date code (1-digit year plus 2-digit week). The transition to the 4-digit date code format is necessary to eliminate confusion as to the year of product assembly (seal). This change will be implemented beginning with date code 1013.

Marking examples:



Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product marked in either manner (3-digit or 4-digit date code) until depletion of existing inventory.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Jon Brewster

Jon Brewster
Intersil Corporation

PA10040

CC: J. Touvell P. Chesley D. Timmerman E. Mashintonio

Products Affected - PA10040

IS9-705RH-8
IS9-705RH-8S2732
IS9-705RH-8S9000
IS9-705RH-Q
IS9-705RH-QS2732
IS9-705RH-QS9000
IS9-705RH-QS9002
5962R0053801QXC
5962R0053801VXC