

# **PRODUCT ADVISORY**

## **Data Sheet Specification Change for Intersil Product ISL55112\***

**Refer to:  
PA10044**

**Date: May 4, 2010**

May 4, 2010

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Change for Intersil Product ISL55112\***

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL55112\* products. The update adds a recommendation for the use of the power down feature when clocking is not needed for the CCD device for several minutes or hours as extended operation in a static condition with the drivers turned on may result in a sub nanosecond timing skew when re-activating dynamic operation. Modifications to the data sheet specification incorporating the changes are complete. The updated data sheet, FN6649 dated May 3, 2010, is included as a separate attachment with the changes shaded in yellow.

Products affected: **ISL55112IRTZ ISL55112IRTZ-T**

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for screening of material supplied today.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

*Jon Brewster*

Jon Brewster  
Intersil Corporation

PA10044

CC: J. Touvell D. LeClair C. Ludeman R. Grist