

Product Change Notice (PA)

Subject: Firmware update for the Renesas ISL68233*, ISL68236*, ISL68239* Products

Publication Date: 10/7/2021

Effective Date: 10/7/2021

Revision Description:

Initial Release

Description of Change:

This notice is to inform you that the firmware for the listed ISL68233*, ISL68236*, ISL68239* products has been updated.

Affected Products List:

ISL68233IRAZ	ISL68236IRAZ	ISL68239IRAZ	ISL68239IRAZ-T7A
ISL68233IRAZ-T	ISL68236IRAZ-T	ISL68239IRAZ-T	

Reason for Change:

This notice is to inform you of a change in internal firmware to improve the following:

- Copies the programmed PMBus voltage (VOUT_COMMAND) to AVSVOUT when starting in AVS mode.

Old firmware rev is 2.0.0.8

NEW firmware rev is 2.0.0.9

The firmware change is internal and does not affect the user's configuration and settings. It is a transparent upgrade for AVSBus mode only as described above.

Impact on fit, form, function, quality & reliability:

The change will have no impact on the form, fit, function, quality, reliability and environmental compliance of the devices.

Product Identification:

Product affected by this change is identifiable via an internal traceability system.

Qualification status: No design change, verification completed.

Sample availability: 10/7/2021

Device material declaration: Available upon request

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Intersil within 30 days of the publication date.

For additional information regarding this notice, please contact your regional change coordinator (below)			
Americas: PCN-US@Renesas.COM	Europe: PCN-EU@Renesas.COM	Japan: PCN-JP@Renesas.COM	Asia Pac: PCN-APAC@Renesas.COM