

RENESAS TECHNICAL UPDATE


Renesas Electronics Corporation
 1753 Shimonumabe, Nakahara-Ku, Kawasaki,
 Kanagawa 211-8668, Japan
 Contact Us <http://japan.renesas.com/contact/>
 E-mail: csc@renesas.com

Product classification	MPU & MCU	Document No.	TN-V85-A027A/E	Rev.	1.00
Title	Document Modification of Standard Self Programming Flow		Notification classification	Technical Information	
Affected Products	In the main part	Affected production lot	Related documents	User's Manual : Hardware of affected products	
		All lots			

In the User's Manual: hardware of V850 Series on the following 2.Affected Products about a standard self-programming flow of the flash memory, we correct it as follows, because there is an error of description about the prohibition of the standby mode.

1. Notification

We correct from "Disable setting of standby mode other than the HALT mode" to "Disable setting of standby mode".



Standard Self Programming Flow

2. Affected Products

Products series		
V850ES/SG3 series	V850ES/SJ3 series	V850E/Sx3-H series