

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

(Note)

URL described on the body is not active.

Please download the update program from the following URL.

http://www.renesas.com/fmwk.jsp?cnt=/download_search_results.jsp&fp=/support/downloads/download_results&layerId=1050

date: 2002/03/11

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development Environment			No	TN-FPS-005A/E	
THEME	Flash Development toolkit Ver2.0.001	Classification of Information	① Spec change 2. Supplement of Documents 3. Limitation of Use	4. Change of Mask 5. Change of Production Line		
PRODUCT NAME	HS6400FDIW2SR	Lot No.	Reference Documents	ADE-702-277	Rev.	Effective Date
		Ver.2.0			1.0	Permanent

The Flash Development toolkit has been updated from Ver. 2.0 to Ver. 2.0.001

The following components have been updated.

(1) Supporting new devices

Supported devices for Ver.2.0

SH7018F, SH7052F, SH7053F, SH7054F, SH7055F, SH7065F,
H8/3022F, H8/3052F, H8/3062AF, H8/3064F, H8/3664F, H8S/2134AF, H8S/2138AF,
H8S/2144AF, H8S/2147AF, H8S/2148AF, H8S/2149YF, H8S/2169YF, H8S/2199F,
H8S/2214F, H8S/2238F, H8S/2258F, H8S/2318F, H8S/2328F, H8S/2338F,
H8S/2623F, H8S/2626F, H8S/2633F, H8S/2636F, H8S/2643F, H8S/2646F, H8S/2676F

Added new devices for Ver.2.0.001

H8S/2215F, H8S/2268F, H8S/2314F, H8S/2315F, H8S/2329F, H8S/2329BF, H8S/2329EF,
H8S/2339F, H8S/2339EF, H8S/2612F, H8S/2648F, H8S/2667F,
H8/3048BF, H8/3052BF, H8/3062BF, H8/3064BF, H8/3068F, H8/3670F, H8/3672F

(2) Fixed programming error

Ver.2.0 output the error message "Write image error", " Erase error" with 3664F user programming mode and could not program or could not erase data.

Ver2.0 user can get the update program from the following URL.

http://www.hitachisemiconductor.com/jp/eng/dev_env