

Exclusively for design purposes; no part of this may be disclosed to a third party without the consent of NEC Electronics (Europe).

<b>Concerned Products:</b>  <i><b>IE-703003-MC-EM1</b></i>	<b>Customer Notification</b>		Date: Mar 09 <sup>th</sup> 98
			NEC-Electronics (Europe) GmbH EAD –Technical Product Support
	<b>Bug Report</b>		Source Doc: BP-070897, SBG-T-0467
			Author: H.-W. Hoeft
Date of initial issue: Oct 24 <sup>th</sup> 97		Doc. No.: TPS-HE-B-2601	

Exclusively for design purposes; no part of this may be disclosed to a third party without the consent of NEC Electronics (Europe).

## (A) BUG LIST

Bug No.		Outline	EM1 board	
			1.21	1.24
1		853 Timer bug	☛	☞

✓: No problem

☞: Bug (corrected by version upgrade)

☛: Bug (restriction, not corrected by version upgrade)

**(B) BUG DESCRIPTION**

Bug No.	Outline	Discription
1	Incorrect Capture Timer Function (V853 Timer Unit)	<u>Details</u> During count-up operation of TM13 the capture operation of CC132 will fail. The data captured into CC132 is not valid. <u>Workaround</u> Don't use capture function of CC132