

RENESAS TOOL NEWS on November 16, 2004: RSO-M38000T2-CPE-041116D

On Problems Found in Reading the CD Included with Compact Emulator M38000T2-CPE

We inform you of the problems found in reading the CD included with the M38000T2-CPE, the compact emulator for the 740 family of MCUs.

1. Products Concerned

All the following CDs included with the M38000T2-CPE:
Code "CPE8000-031216" is printed on the label.

However, the problems have been resolved in the CDs shipped on and after November 8, 2004.

2. Description

The following symptoms may arise in the CDs concerned:

- (1) You cannot read characters in the README_E.TXT file when opening it.
- (2) Clicking the setup.exe file does not start the program installation.

If you are experiencing these symptoms in your CD, please e-mail

csc@renesas.com

with the following items of information:

Your name:

Your section:

Your company:

Your local Renesas Technology sales office or distributor:

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.