

[Upgrade to revision]

R20TS0534EJ0100

Rev.1.00

Jan. 16, 2020

e² studio Code Generator Plug-in V2.15.0,

AP4 Coding Assistance Tool for RZ V1.09.00

Outline

The products in the title have been updated as follows.

- (1) e² studio Code Generator plug-in: V2.14.0 to V2.15.0
- (2) AP4 for RZ: V1.08.00 to V1.09.00

1. Products and Versions to Be Updated

- e² studio V7.6.0 (Code Generator plug-in V2.14.0) and earlier versions
- AP4 for RZ V1.08.00 and earlier versions

2. Description of the Update

The main features of the update are described in the following sections. See the release note for details.

- RZ Code Generation Tools
 - e² studio Code Generator plug-in V2.15.0
 - AP4 for RZ V1.09.00 Release Note (Scheduled to be released on January 20.)

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4676>

Note: Windows7 support has ended with RZ Code Generation Tools as Microsoft ended support for Windows7.

2.1 Issues Fixed

The following issues have been fixed.

- (1) RENESAS TOOL NEWS Document number R20TS0398EJ0100

1. Point for caution regarding the write value of RSPI status register (SPSR)

Applicable devices: RZ/T1 group

For details about this issue, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0398>

- (2) RENESAS TOOL NEWS Document number R20TS0422EJ0100

1. Using link mode of DMAC

Applicable devices: RZ/T1 group

For details about this issue, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0422>

(3) RENESAS TOOL NEWS Document number R20TS0525EJ0100

1. Writing 0 to the timer dead time enable register in multi-function timer pulse unit 3 (MTU3a)

Applicable devices: RZ/T1 group

For details about this issue, refer to the URL below.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0525>

3. Updating Your Product

The update method varies depending on your product.

For details, see the following. The updates are available free of charge.

3.1 Updating e² studio Code Generator Plug-in

For how to update e² studio, refer to "3. Updating Your Product" in RENESAS TOOL NEWS Document number R20TS0532EJ0100. (Scheduled to be released on January 20.)

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0532>

Note that Code generator plug-in cannot be updated by itself.

3.2 Updating AP4 for RZ

Download the installer from the following URL to install the update.
(The installer will be available from January 20.)

https://www.renesas.com/aplilet_download

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jan.16.20	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,

Koto-ku, Tokyo 135-0061, Japan

www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.