
[Upgrade to Revision]

R20TS1044EJ0100

Rev.1.00

Jul. 20, 2024

e² studio RL78 Smart Configurator Plug-in 2024-07

Smart Configurator for RL78 V1.11.0

Outline

The products in the title have been updated as follows.

- (1) e² studio RL78 Smart Configurator Plug-in: From 2024-04 to 2024-07
- (2) Smart Configurator for RL78: From V1.10.0 to V1.11.0

1. Products to Be Updated

- e² studio 2024-04 (RL78 Smart Configurator Plug-in 2024-04) and earlier
- Smart Configurator for RL78 V1.10.0 and earlier

2. Description

The following issue has been fixed.

- Fixed the issue of displaying wrong top view picture in [MCU/MPU Package] page and wrong pin number information in [Pins] page
- Fixed the issue of displaying the uncorrect status of unsupported components (FAA, SMS, ELCL) in [Overview] page after changing device
- Fixed the issue of the pin information in [Pins] page maybe wrong after changing device
- Fixed the issue of the pin IVREF0 and IVREF1 are conflicted among Comparator 0 - 3
- Fixed the issue of the API R_Config_RTC_Get_CounterValue () and R_Config_RTC_Set_CounterValue () are unable to break out of the loop when using Alarm function

For other fixes, please refer to the release notes above.

- Smart Configurator for RL78
Smart Configurator for RL78 V1.11.0 Release Note (the note will be uploaded on July 22)
<https://www.renesas.com/software-tool/rl78-smart-configurator#documents>

3. Updating the Product

Refer to the following and update accordingly. The products can be updated free of charge.

3.1 CS+

- (1) Download the latest Smart Configurator for RL78 from the URL below and install it (V1.10.0 will be released on July 22).

<https://www.renesas.com/rl78-smart-configurator#downloads>

Smart Configurator for RL78 V1.11.0

- (2) On the Windows Start menu, select Programs, Renesas Electronics CS+, and then run the Update Manager (this service will be available from July 22).

Note: If you have started CS+ with the Rapid Startup function enabled, exit CS+, and then start the Update Manager.

If the Rapid Startup function is enabled and the CS+ icon is shown in the Windows notification area, the following error occurs.

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

3.2 e² studio

Refer to the Tool News (3. Updating the Product) at the URL below (the news will be uploaded on July 22).

<https://www.renesas.com/software-tool/e-studio#documents>

RENESAS TOOL NEWS: R20TS1041EJ0100 (July 22, 2024, issue)

e² studio Integrated Development Environment 2024-07 Update

Note: The Smart Configurator is up

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jul.20.24	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.