

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda -ku, Tokyo 100-0004, Japan
Renesas Technology Corp.

Product Category	MPU&MCU		Document No.	TN-H8*-A306A/E	Rev.	1.00
Title	H8S/2218 Group BP-112,BP-112V Pin No. mistake.		Information Category	Technical Notification		
Applicable Product	H8S/2218 Group	Lot No.	Reference Document	H8S/2218, H8S/2212 Group Hardware Manual (REJ09B0074-04000 Rev.4.00)		
		All				

There is the error in the description about pin no. in I/O port (P70).

< Hardware manual change part >

· Section 1.5 Pin Functions (page 26 of 692)

Type	Symbol	Pin No.		I/O	Function
		TFP-100G	BP-112		
I/O port	P77	-	-	52	3-bit I/O pins
	P76	-	-	53	
	P75	-	-	54	
	P74	55	H9	-	
	P71	56	H10	-	
	P70	63	H11	-	



Type	Symbol	Pin No.		I/O	Function
		TFP-100G	BP-112		
I/O port	P77	-	-	52	3-bit I/O pins
	P76	-	-	53	
	P75	-	-	54	
	P74	55	H9	-	
	P71	56	H10	-	
	P70	63	F11	-	