

RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RZ*-A040A/E	Rev.	1.00
Title	RZ/A1 Series: Notes about S0_WLINE interrupt and S1_WLINE interrupt of Video Display Controller 5		Information Category	Technical Notification		
Applicable Product	See following	Lot No.	Reference Document	See following		
		All				

In RZ/A1H Group, RZ/A1M Group, RZ/A1L Group and RZ/A1LU Group, a bug about S0_WLINE interrupt and S1_WLINE interrupt of Video Display Controller 5 (VDC5) is found.

Notes about S0_WLINE interrupt and S1_WLINE interrupt of Video Display Controller 5 (VDC5) are as follows.

According to this update, relevant manuals will be revised.

Applicable products and relevant documents

Applicable products		Relevant documents	Rev.	Document number
series	Group			
RZ/A	RZ/A1H, RZ/A1M	RZ/A1H Group, RZ/A1M Group User's Manual: Hardware	Rev 3.00	R01UH0403EJ0300
	RZ/A1L, RZ/A1LU	RZ/A1L Group, RZ/A1LU Group, RZ/A1LC Group User's Manual: Hardware	Rev 3.00	R01UH0437EJ0300

[1] Condition

When S0_WLINE interrupt or S1_WLINE interrupt is used.

[2] Phenomenon

S0_WLINE interrupt or S1_WLINE interrupt may not occur.

[3] Restriction

Using S0_WLINE interrupt and S1_WLINE interrupt is prohibited.

End of document