

RENESAS TOOL NEWS on August 07, 2015: 150807/tn5

Revisions to the Following Tools CS+ Code Generator for RL78 (CS+ for CC) CS+ Code Generator for RL78 (CS+ for CA, CX) Code Generator Plug-in for the e2 studio AP4 Coding Assistance Tool for RL78

We are revising the CS+ Code Generator for RL78 (CS+ for CC) from V2.08.00 to V2.09.00, the CS+ Code Generator for RL78 (CS+ for CA, CX) from V2.08.00 to V2.09.00, the e2 studio (Code Generator Plug-in) from V2.0.1 to V2.0.2, and the AP4 Coding Assistance Tool for RL78 from V1.07.00 to V1.08.00.

1. Applicable Products

- CS+ Code Generator for RL78 (CS+ for CC), V2.08.00 and earlier revisions
- CS+ Code Generator for RL78 (CS+ for CA, CX), V2.08.00 and earlier revisions
- e2 studio V4.0.1.007, (Code Generator Plug-in, V2.0.1) and earlier revisions
- AP4 Coding Assistance Tool for RL78 V1.07.00 and earlier revisions

2. Descriptions of Revision

The following group has been added to the set of supported MCUs.

- RL78 family: RL78/G1D group

3. Updating Your Product

The method of updating differs with the product you are using. Refer to the following description for the details. Both methods of updating are free of charge.

3.1 Updating the CS+ Code Generator for RL78

To update either your commercial or evaluation edition of CS+, use either of the following methods.

If your product is CS+ V3.00.00 or an earlier version, you will also need to update your CS+ to V3.01.00 in advance.
Please download and install the evaluation edition of CS+ V3.01.00 from the following URL:
https://www.renesas.com/cs+_download

(1) Use the Update Manager

On the "Start" menu, select "Programs" and then "Renesas Electronics CS+" to start the Update Manager.

This service will be available from August 07, 2015.

Note:

If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, attempting to run the Update Manager produces an error and the following message.

M0120001

Installation is suspended because "CubeSuiteW+.exe" is running.
It will be resumed next time you start the tool.

(2) Download the installer of the product from our Web site

Download the CS+ Code Generator for RL78 (CS+ for CC) V2.09.00 or the CS+ Code Generator for RL78 (CS+ for CA, CX) V2.09.00 from the URL below to install the program.

The program will be available from August 07, 2015.

https://www.renesas.com/cs+_download

3.2 Updating the e2 studio (Code Generator Plug-in)

Refer to RENESAS TOOL NEWS document number 150807/tn2 "3. Updating Your Product" for details of how to update the e2 studio. This information will be available on the Web from August 07, 2015.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=150807tn2>

Note that only updating the Code Generator Plug-in is not possible.

3.3 Updating the AP4 Coding Assistance Tool for RL78

Download the installer from the URL below to install the program.

The program will be available from August 07, 2015.

https://www.renesas.com/applilet_download

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.