

[Upgrade to revision] RH850 Smart Configurator V1.4.0

R20TS0707EJ0100
Rev.1.00
May. 16, 2021

Overview

The product in the title will be revised and its version number will be changed as follows:

- (1) RH850 Smart Configurator: V1.3.0 to V1.4.0

1. Version to Be Updated

- All revisions up to V1.3.0 of RH850 Smart Configurator

2. Items Revised

The major revision points are as follows. Refer to the following release note for details.

<https://www.renesas.com/software-tool/smart-configurator#documents>

RH850 Smart Configurator V1.4.0 Release Note. This information will be released on May 20.

2.1 Description of Modification

The problems regarding the points below have been fixed.

- (1) RENESAS TOOL NEWS, Document No. R20TS0668EC0100

1. When Using CSI Master

For details about the problems, refer to the following URL:

<https://www.renesas.com/document/tnn/notes-smart-configurator-rh850-4>

- (2) RENESAS TOOL NEWS, Document No. R20TS0679EC0100

- 1. When using CSI Master and CSI Slave with CSIG
- 2. When using CSI Master with CSIH
- 3. When using Data CRC
- 4. When using One-Pulse Output and One-Shot Pulse Output
- 5. When using PWM Output and Triangle PWM Output

For details about the problems, refer to the following URL:

<https://www.renesas.com/document/tnn/notes-smart-configurator-rh850-5>

3. How to Update Your Copy

To update your program, use either of the following methods:

- (1) Download RH850 Smart Configurator from the following URL, and then install the program.

The program will be available from May 20.

<https://www.renesas.com/smart-configurator#downloads>

Smart Configurator for RH850 V1.4.0

- (2) From the Windows Start menu, select Renesas Electronics CS+ to start the Update Manager and update the program. This service will be available from May 20.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.
If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	May.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.