RENESAS Tool News

RENESAS TOOL NEWS on September 1, 2011: 110916/tn7

Corrections to Additional Document for User's Manual of E1 Emulator: Notes on Connection with V850E2M

Summary We inform you about corrections to the additional document for the E1 emulator user's manual: notes on connection with the V850E2M MCUs

1. Document Concerned

Document No. R20UT0539EJ0100

"E1 Emulator Additional Document for User's Manual (Notes on Connection) Supported Devices: V850E2M"

2. Corrections

(1) Page 7, Figure 2-2

The No. 10 pin female of the emulator's connector, which is "Not Connected," must be connected to the RESET pin of the MCU.

(2) Page 9, Figure 2-4 The same as in (1).

3. Note

You can see the user's manual Document No. R20UT0539EJ0100 to which these corrections have already been made on the Web site at: http://www.renesas.com/products/tools/emulation_debugging/onchip_debuggers/e1/Docu

The above URL is one of our global sites.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 \circledast 2010-2016 Renesas Electronics Corporation. All rights reserved.