

RENESAS TOOL NEWS [RSO-M3T-PD38_1-030516D]

A Note on Using Emulator Debugger M3T-PD38 V.5.10 Release 2

Please take note of the following problem in using the M3T-PD38 emulator debugger for the 740 family MCUs:

• On verifying your license ID at launching the M3T-PD38

1. Versions Concerned

M3T-PD38 V.5.10 Release 2

2. Description

At launching the M3T-PD38, an error message "LICENSE ERROR: License information is not found. Please install again!" may be displayed, failing in the launch.

3. Condition

This problem occurs if the M3T-PD38 V.5.10 Release 2 is launched with the M3T-PD38 V.5.10 Release 1 or 1A being not installed in the host machine.

Note:

When the M3T-PD38 is used with the PC4701M or PC4701U emulator, it does not verify your license ID, and this problem does not occur.

4. Schedule of Fixing the Problem

This problem has been fixed in the M3T-PD38 V.5.10 Release 2A, the upgraded version. It can be downloaded from HERE.

For information on the M3T-PD38 V.5.10 Release 2A, see RENESAS TOOL NEWS "Emulator Debugger M3T-PD38 V.5.10 Release 2A Upgraded" issued at this time.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 $\ @\ 2010\mbox{-}2016$ Renesas Electronics Corporation. All rights reserved.