Rev.1.00

R20TS0451EJ0100 [Notes] RX64M Group Jul. 16, 2019 TCP/IP Protocol Stack Based Network Solution for Industrial Applications **RX Driver Package Application** RX64M, RX71M Group TCP/IP Protocol Stack Based Network Solution for Industrial Applications **RX Driver Package Application**

Outline

When using the products in the title, note the following point.

- 1. When calling the "R ETHER Read ZC2 BufRelease" function or "R ETHER Read" function
- 1. When Calling the "R ETHER Read ZC2 BufRelease" Function or "R ETHER Read" **Function**

1.1 Applicable Products

 \triangleright Sample programs that includes the Ethernet FIT module

The product names and revision numbers of the applicable sample programs and the revision numbers of the included Ethernet FIT module are listed below.

Sample program product name	Document number
RX64M Group TCP/IP Protocol Stack Based Network Solution for Industrial Applications RX Driver Package Application Rev.1.00	R01AN2153EJ0100
RX64M, RX71M Group TCP/IP Protocol Stack Based Network Solution for Industrial Applications RX Driver Package Application Rev.1.03 and earlier versions	R01AN2608EJxxx*

Table 1.1	Products that includes the Ethernet FIT module
-----------	--

*: xxxx indicates the (revision) number 0103 or below.

1.2 Applicable Devices

RX63N, RX65N, RX64M, and RX71M groups

1.3 Details, Conditions and Workaround

The error occurs in the RX family Ethernet module using Firmware Integration Technology (r_ether_rx) included in the sample program.

For details, see RENESAS TOOL NEWS, Document No. R20TS0447EJ0100 section 1.3 through 1.5.

https://www.renesas.com/search/keyword-search.html#genre=document&documenttype=531&q=r20ts0447 [Notes]

RX Family

Ethernet Module Using Firmware Integration Technology, RX Driver Package

1.4 Schedule for Fixing the Problem

This problem will be fixed in a later version.



Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Jul.16.19	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

URLs in Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

© 2019. Renesas Electronics Corporation. All rights reserved. TS Colophon 4.0

