RENESAS Tool News

RENESAS TOOL NEWS on July 1, 2007: 070701/tn9

Notes on Using Flash Development Toolkit

Please take note of the problems described below in using Flash Development Toolkit. (This toolkit is used for writing programs into flash memories in the SuperH RISC engine, M16C, H8SX, H8S, H8, and 740 families of MCUs.)

1. Product and Versions Concerned

Flash Development Toolkit V.3.05 through V.3.07

2. Descriptions

If the user system is equipped with the COM1 port and any COM1* ports other than COM1 (for example, COM10, COM11, COM100, and so on; "*" means the wild-card), COM1 cannot be selected in the "Select port" drop-down list in the Communication Port dialog because COM1 is not provided in the list.

And if the user system is equipped with the COM2 port and any COM2* ports other than COM2 (for example, COM20, COM21, COM200, and so on; "*" means the wild-card), COM2 cannot be selected in the "Select port" drop-down list in the Communication Port dialog because COM2 is not provided in the list.

3. Workaround

Delete COM1* and COM2*.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.