

RENESAS TOOL NEWS on August 1, 2014: 140801/tn4

Applilet3 for RL78 Revised

We have revised the Applilet3 for RL78 from V1.04.00 to V1.05.00.

1. Descriptions of Revision

(1) Device Support

The following RL78 family MCUs have been added to the support line:

In the RL78/G14 group:

Products with equal to or greater than 384-KB ROM

(2) Problems Fixed

The following problems, of which we informed you in RENESAS TOOL NEWS Document No. 140416/tn8, have been fixed:

- With selecting the 20-pin, 30-pin, or 32-pin package for the RL78/F13 or RL78/F14 group
- With using the remote control carrier wave mask signal in the RL78/L12 group
- With the case when ports that are not available in the MCU are displayed in the RL78/G14 group

For details of these problems, see the following page:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=140416tn8>

2. Updating Your Product

Download the installer of the product from the following URL:

https://www.renesas.com/applilet_download

The installer will be available on this site from August 5.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.