# [Upgrade to revision]

R20TS0153EJ0100 Rev.1.00 Apr. 1, 2017

# Device Information (Managed by CS+) for RH850 Family

V5.00.01

#### **Outline**

We will be revising the device information file (managed by CS+) for the RH850 family from V5.00.00 to V5.00.01.

#### 1. Products and Versions to Be Updated

- ➤ Device information file managed by CS+ for the RH850 family (CS+ Device Information for RH850) V3.00.00 or later
- ➤ Device information file managed by CubeSuite+ for the RH850 family (CubeSuite+ DevInfo\_RH850) V1.00.04 or earlier

Check your version number of "CS+ Device Information for RH850" or "CubeSuite+ DevInfo\_RH850" with reference to the procedure described under the heading "Components" at the URL below.

https://www.renesas.com/cs+\_ver

#### 2. Description of Revision

The major revision points are as follows. Refer to the page at the URL below for details.

The information will be available from April 5. https://www.renesas.com/cs+/eng/CSPlus DevInfo RH850.html

## 2.1 Addition of Supported MCUs

The following group of MCUs has been added to the supported line.

- RH850/V1R-M group (RH850 family)

Support for some MCUs of the following groups has been added.

- RH850/P1H-C group (RH850 family)
- RH850/P1M-C group (RH850 family)

## 2.2 Description of Modification

The SFR information for the following group has been modified.

- RH850/P1M-E group (RH850 family)

## 3. Updating Your Product

Online updating is available free of charge. The method of updating depends on the edition of CS+.

#### 3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

(1) On the "Start" menu, select "Programs" and then "Renesas Electronics CS+" to start the Update Manager. This service will be available from April 5.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

(2) Download and install the software tools you want from the web site at the following URL.

The program will be available from April 5.

https://www.renesas.com/cs+\_download

#### 3.2 For CubeSuite+ from V2.00.00 to V2.02.00

Update your program in the same way as is described in 3.1 above.

#### 3.3 For CubeSuite+ V1.03.00 or Earlier

Download either of the evaluation editions of CS+ for CC V5.00.00 and CS+ for CA,CX V4.00.00, then update your program. The program will be available from April 5.

https://www.renesas.com/cs+\_download

## **Revision History**

		Description	
Rev.	Date	Page	Summary
1.00	Apr. 1, 2017	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

#### ■Inquiry

https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2017 Renesas Electronics Corporation. All rights reserved.

TS Colophon 2.0