

RENESAS TOOL NEWS on January 10, 2008: 080110/tn1

A Note on Using High-performance Embedded Workshop V.4.04.00

Please take note of the problem described below in using High-performance Embedded Workshop V.4.04.00.

1. Problem

When your High-performance Embedded Workshop updated to V.4.04.00 is launched, it may be terminated abnormally.

2. Conditions

This problem occurs if the following conditions are both satisfied:

- (1) The Find In Files facility* had ever been used in your High-performance Embedded Workshop before it was updated to V.4.04.00.
- (2) The Directory pull-down list in the Find In Files dialog box contains 5 or 9 histories of specified directories.

*The Find In Files facility searches for the specified character string in the specified file. It can be accessed by opening the Edit menu of High-performance Embedded Workshop.

3. Workaround

Download the Hew_V40400 script file from the Web site (FAQ pages) shown below. Then copy the file to the directory where High-performance Embedded Workshop V.4.04.00 resides and execute it (double-click the file's icon).

Web site: FAQ 106852

4. Schedule of Fixing the Problem

We plan to fix this problem in the next release of the product.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 $\ @\ 2010\mbox{-}2016$ Renesas Electronics Corporation. All rights reserved.