

RENESAS TOOL NEWS on January 16, 2005: RSO-E6000H-050116D

## The E6000H's Emulator Software Products for the H8SX Family Revised to Their V.3.03 Release 01

We have revised the E6000H's emulator software products for the H8SX family of MCUs from their V.3.02 Release 00 to V.3.03 Release 01. (Those products are used for the H8SX/1650, H8SX/1520, and H8SX/1580 groups.)

---

### 1. Products Concerned

The following types of the E6000H's emulator software products for the H8SX family of MCUs are concerned:

- HS1650EPH60H (specific to the H8SX/1650 group)
- HS1527KEPH60H (specific to the H8SX/1520 and H8SX/1580 groups)

### 2. Descriptions of Revision

#### 2.1 Newly Supported Devices

The H8SX/1582 has been added to the device support of the HS1527KEPH60H.

#### 2.2 Functions Modified

- (1) The trigger outputting function for on-chip breaks has been removed from the products because the E6000H emulator for the H8SX family does not support this function.
- (2) The problem on displaying events for breaks has been resolved which arises after the event count for an on-emulator break is specified.

### 3. How to Get and Install Revised Products

- (1) Download the update program for those products from the Download Site
- (2) Execute the downloaded update program, and the installer will be invoked. Then, follow the instructions of the installer to install the product(s) you want.

---

#### **[Disclaimer]**

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.