

## A Note on Using AutoUpdate Utility

Please take note of the following problem in using AutoUpdate Utility:

- With updating the C/C++ compiler packages for the SuperH family, and the H8SX, H8S, and H8 families of MCUs
- 

### 1. Description

Even when you have updated a compiler package using AutoUpdate Utility, the Updater of the compiler package may be detected by the utility.

### 2. Conditions

This problem occurs in both the following cases:

- (1) The C/C++ compiler package for the SuperH family has been updated from V.9.01 Release 00 to V.9.01 Release 01 using AutoUpdate Utility.
- (2) The C/C++ compiler package for the H8SX, H8S, and H8 families has been updated from V.6.01 Release 03 to V.6.02 Release 00 using AutoUpdate Utility.

### 3. Workaround

If you encounter this problem, perform the following procedure to change the settings of AutoUpdate Utility:

- (1) Invoke AutoUpdate Utility. The "Welcome to AutoUpdate Wizard" window opens.
- (2) Click the Next button. The window for selecting applications appears.
- (3) Uncheck the check boxes for the following products to be updated in the Applications list:

- (1) Application name:

C/C++ compiler package for SuperH RISC engine family  
Version No.: 9.01.00

(2) Application name:

C/C++ compiler package for the H8, H8S, and H8SX

Version No.: 6.01.03

(4) Click the Next button. The search window for updating information appears.

(5) Click Next to open The Finished window.

(6) Click the Finish button.

#### **4. Schedule of Fixing the Problem**

We plan to fix this problem in the next release of both products.

---

#### **[Disclaimer]**

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.