

RENESAS TECHNICAL UPDATE

1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-32R-A080A/E	Rev.	1.00
Title	32176 Group Hardware Manual Errata Rev.A		Information Category	Technical Notification		
Applicable Product	32176 Group	Lot No.	Reference Document	32176 Group Hardware Manual REV.1.10 (REJ09B0067-0110)		

Since we corrected the contents of "32176 Group Hardware Manual REV.1.10 (Publish in January, 2006)", we announce you.

Please use attached errata for "32176 Group Hardware Manual REV.1.10" in the case of use.

Appending Document:" 32176 Group Hardware Manual REV.1.10" errata Rev.A ... 1 sheet

Rev.	Page	Part	Contents				
REV.A	3-4	CHAPTER 3 ADDRESS SPACE 3.2 Operation Modes	Error	<p>Fig. 3.2.1 Address space of the M32176F4, "H'008F 9FFF" (Error) in a figure</p>			
				Correction	<p>Fig. 3.2.1 Address space of the M32176F4, "H'0080 9FFF" (Correction) in a figure</p>		
REV.A	3-5	CHAPTER 3 ADDRESS SPACE 3.2 Operation Modes	Error		<p>Fig. 3.2.2 Address space of the M32176F3, "H'008F 9FFF" (Error) in a figure</p>		
				Correction	<p>Fig. 3.2.2 Address space of the M32176F3, "H'0080 9FFF" (Correction) in a figure</p>		
REV.A	3-6	CHAPTER 3 ADDRESS SPACE 3.2 Operation Modes	Error		<p>Fig. 3.2.3 Address space of the M32176F2, "H'008F 9FFF" (Error) in a figure</p>		
				Correction	<p>Fig. 3.2.3 Address space of the M32176F2, "H'0080 9FFF" (Correction) in a figure</p>		