

To our customers,

---

## Old Company Name in Catalogs and Other Documents

---

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1<sup>st</sup>, 2010  
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

# RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan  
Renesas Technology Corp.

Product Category	MPU&MCU		Document No.	TN-SH7-A627A/E	Rev.	1.00
Title	The error correction about unused USB pins of USB2.0 Host/Function Module (USB).		Information Category	Technical Notification		
Applicable Product	R5S72630P200FP	Lot No.	Reference Document	<ul style="list-style-type: none"> <li>• SH7263 Group Hardware Manual Rev.1.00 (REJ09B0290-0100)</li> <li>• SH7203 Group Hardware Manual Rev.1.00 (REJ09B0313-0100)</li> </ul>		
	R5S72631P200FP	ALL				
	R5S72632P200FP					
	R5S72633P200FP					
	R5S72030W200FP					

We would like to inform you of the following error correction about unused USB pins of USB2.0 Host/Function Module (USB) included in the above-mentioned applicable products.

Following shows error correction about unused USB pins.

[Error]

Connect REFRIN to USBAPVss through a 5.6k $\Omega$   $\pm$  1% resistor.

[Correction]

Connect REFRIN to USBAPVcc through a 5.6k $\Omega$   $\pm$  1% resistor.