

RENESAS TECHNICAL UPDATE


1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-SH7-A844A/E	Rev.	1.00
Title	Error correction of the TEIE and MPIE bits of SCIF		Information Category	Technical Notification		
Applicable Product	SH7709 Group SH7709A Group SH7729 Group SH7706 Group SH7709S Group SH7729R Group	Lot No.	Reference Document	SH7709 Group Hardware Manual Rev.2.00 (ADE-602-123B) SH7709A Group Hardware Manual Rev.5.00 (ADE-602-187D) SH7729 Group Hardware Manual Rev.4.00 (ADE-602-157C) SH7706 Group Hardware Manual Rev.5.00 (REJ09B0146-0500) SH7709S Group Hardware Manual Rev.5.00 (REJ09B0081-0500) SH7729R Group Hardware Manual Rev.5.00 (REJ09B0091-0500)		
		All				

We would like to inform you to correct the clerical error of the serial communication interface with FIFO (SCIF) of a hardware manual.

TEIE and MPIE bits in a figure "Sample Flowchart for SCIF Initialization" are deleted.

[Error]



[Correction]

