

To our customers,

---

## Old Company Name in Catalogs and Other Documents

---

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1<sup>st</sup>, 2010  
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

(Note)

URL described on the body is not active. Please refer to following URL.

[http://www.renesas.com/fmwk.jsp?cnt=/download\\_search\\_results.jsp&fp=/support/downloads/download\\_results&layerId=1182](http://www.renesas.com/fmwk.jsp?cnt=/download_search_results.jsp&fp=/support/downloads/download_results&layerId=1182)

date:2002/03/27

# HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development Environment		No	TN-EML-082A/E		
THEME	Information on a Malfunction and Version Update of the SH7750R E10A Emulator and the SH7751R E10A Emulator	Classification of Information	1. Spec change 2. Supplement of Documents 3. Limitation of Use	4. Change of Mask 5. Change of Production Line		
PRODUCT NAME	SH7750R SH7751R	Lot No.	Reference Documents	None	Rev.	Effective Date
		All lots			—	Permanent

A Timeout error occurred when a breakpoint has been set in the SH7750R E10A emulator and The SH7751R E10A emulator.

Type numbers of the target products:

SH7750R E10A emulator V1.00

Type number: HS7750RKCM01H  
HS7750RKCI01H

SH7751R E10A emulator V1.00

Type number: HS7751RKCM01H  
HS7751RKCI01H  
HS7751RKCM02H  
HS7751RKCI02H

[Malfunction]

When the EMODE bit in the CCR register is 1 and a breakpoint is used, a Timeout error will occur.

We will modify this malfunction and register the software on Hitachi's internet homepage.

If you need the updated version immediately, ask Hitachi's sales agent.

We will provide the file to be replaced in the floppy disk.

URL :

<http://www.hitachisemiconductor.com/sic/jsp/japan/eng/products/mpumcu/tool/download/e10a.html>