

RENESAS TECHNICAL UPDATE

1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan
Renesas Electronics Corporation

| | | | | | | |
|--------------------|-----------------------------------|---------|----------------------|------------------------|------|------|
| Product Category | MPU/MCU | | Document No. | TN-SH7-A796A/E | Rev. | 1.00 |
| Title | Notes on Use of SD Host Interface | | Information Category | Technical Notification | | |
| Applicable Product | See below | Lot No. | Reference Document | See below | | |
| | | All | | | | |

[Applicable Products and Reference Documents]

| Series | Group | Reference Document Title | Rev. | Document No. |
|--------|----------------|---|------|-----------------|
| SH7260 | SH7263 | SH7263 Group Hardware Manual | 3.00 | REJ09B0290-0300 |
| | SH7265 | SH7265 Group Hardware Manual | 2.00 | REJ09B0351-0200 |
| | SH7262, SH7264 | SH7262 Group SH7264 Group Hardware Manual | 2.00 | REJ09B0445-0200 |
| | SH7266, SH7267 | SH7266 Group SH7267 Group Hardware Manual | 1.00 | REJ09B0566-0100 |

We would like to inform you of the notice about SD Host Interface included in the above-mentioned applicable product.

[Notice]

During multiple block read, if performing a force-quit, the command sequence is not terminated depending on the timing of register setting. Renesas Electronics Corporation is only able to provide information contained in this TECHNICAL UPDATE to parties with which we have concluded a nondisclosure agreement. Please contact one of our sales representatives for details.

However, if you use our SD memory card driver (following table), it doesn't correspond to this phenomenon.

| Group | SD memory card driver Part No. |
|----------------|--------------------------------|
| SH7263 | R0M7263DS0000RRC |
| SH7265 | R0M7265DS0000RRC |
| SH7262, SH7264 | R0M7264DS0000RRC |
| SH7266, SH7267 | R0M7266DS0000RRC |