

Corrections to the HI1000/4 User's Manual

We notify corrections to the HI1000/4 user's manual (Document No. REJ10B0129-0100H, issued on April 21, 2004) as stated below.

1. Corrections

Page 146, Table 4.4

- (1) Add the following statement to the end of the fourth description corresponding to the item of Usable service calls:
No service calls can be issued if the masking level of an interrupt by the CPU-exception handler is higher than that by the kernel.

- (2) Add the following statement to the end of the sixth description corresponding to the item of Termination method:
Or, be terminated by the RTE instruction if the masking level of an interrupt by the CPU-exception handler is higher than that by the kernel.
When the handler is terminated, the stack pointer must be kept in the same conditions as those when the handler was invoked.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.