

RENESAS TOOL NEWS on May 16, 2010: 100516/tn4

A Note on Using E8a Emulator Software V.1.03 Release 04

Please take note of the following problem in using E8a Emulator Software V.1.03 Release 04:

- With debugging systems designed with MCUs of the M16C/5M group encapsulated in a 100-pin package
-

1. Description

If you debug systems designed with any of the following MCUs by using M16C E8a Emulator debugger V.1.03.03, which is included in E8a Emulator Software V.1.03 Release 04, error message "Boot Failed!" or "Communication timeout error" appears when the debugger has been started, and the debugger cannot communicate with the E8a emulator.

MCUs involved (in the M16C/5M group):

- R5F35M16, R5F35M1E, R5F35M66, R5F35M6E, R5F35MA6, R5F35MAE, R5F35MD6, and R5F35MDE

2. Solution

If you use any of the above MCUs, please contact your local Renesas sales office or distributor. We reply to your message individually.

3. Schedule of Fixing the Problem

We will inform you of the schedule of fixing the problem later on RENESAS TOOL NEWS.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.