

## Device Information (Managed by CS+) for RL78 Family Revised to V3.00.03

We are revising the device information file (managed by CS+) for the RL78 family of MCUs and accordingly will change the version number from 3.00.02 to 3.00.03.

---

### 1. Product and Versions to Be Updated

- (1) Device information file managed by CS+ for the RL78 family of MCUs (CS+ for CC Device Information for RL78) V3.00.02 or earlier
- (2) Device information file managed by CS+ for the RL78 family of MCUs (CS+ for CA, CX Device Information for RL78) V3.00.02 or earlier
- (3) Device information file managed by CubeSuite+ for the RL78 family of MCUs (CubeSuite+ DevInfo\_RL78\_78K) V1.00.18 or earlier

Check your version number of "CS+ for CC Device Information for RL78", "CS+ for CA,CX Device Information for RL78", or "CubeSuite+ DevInfo\_RL78\_78K" with reference to the procedure described under the heading "Components" at the URL below.

[https://www.renesas.com/cs+\\_ver](https://www.renesas.com/cs+_ver)

### 2. Description of Revision

The SFR information for the below group was revised.

- RL78 family RL78/I1D group

Refer to the information at the following URL for details.

This page will be updated on September 7, 2015.

[https://www.renesas.com/cubesuite+/CSP\\_DevInfo\\_RL78.html](https://www.renesas.com/cubesuite+/CSP_DevInfo_RL78.html)

### 3. Updating Your Product

Online updating is available free of charge.

To update either your commercial edition or evaluation edition of CS+, use either of the following methods.

### 3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

(1) On the "Start" menu, select "Programs" and then "Renesas Electronics CS+" to start the Update Manager.

This service will be available from September 7.

#### Note:

If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

-----

M0120001

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

-----

(2) Download and install V3.00.03 of the device information file managed by CS+ for the RL78 family of MCUs from the following URL.

The program will be available from September 7.

[https://www.renesas.com/cs+\\_download](https://www.renesas.com/cs+_download)

### 3.2 For CubeSuite+ V2.02.01 and Earlier Versions

Please download and install the evaluation edition of CS+ for CC V3.01.00 or CS+ for CA, CX V3.00.01 (which corresponds to the compiler you are using) from the following URL.

[https://www.renesas.com/cs+\\_download](https://www.renesas.com/cs+_download)

Then, update your program by using the method in 3.1 (1) or (2) above.

---

#### [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.