

RENESAS TOOL NEWS on January 16, 2016: 160116/tn4

Device Information (Managed by CS+) for RL78 Family Revised to V3.00.05

We are revising the device information file (managed by CS+) for the RL78 family of MCUs and accordingly will change the version number from 3.00.04 to 3.00.05.

1. Product and Versions to Be Updated

- (1) Device information file managed by CS+ for the RL78 family of MCUs (CS+ for CC Device Information for RL78) V3.00.04 or earlier
- (2) Device information file managed by CS+ for the RL78 family of MCUs (CS+ for CA, CX Device Information for RL78) V3.00.03 or earlier
- (3) Device information file managed by CubeSuite+ for the RL78 family of MCUs (CubeSuite+ DevInfo_RL78_78K) V1.00.18 or earlier

Check your version number of "CS+ for CC Device Information for RL78", "CS+ for CA, CX Device Information for RL78", or "CubeSuite+ DevInfo_RL78_78K" with reference to the procedure described under the heading "Components" at the URL below.

https://www.renesas.com/cs+_ver

2. Descriptions of Revision

(1) Addition of Supported MCUs

The following has newly been added.

- RL78/G1H group

(2) Correction to SFR Information

SFR information for the groups listed below was corrected.

- RL78/G1C group
- RL78/L1C group
- RL78/G10 group

For details, go to:

http://tool-support.renesas.com/autoupdate/support/eng/cs_plus/DeviceInformation_RL78_List.html

This information will be available from January 20.

3. Updating Your Product

Online updating is available free of charge.

To update either your commercial edition or evaluation edition of CS+, use either of the following methods.

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

(1) On the "Start" menu, select "Programs" and then "Renesas Electronics CS+" to start the Update Manager.

This service will be available from January 20.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

Installation is suspended because "CubeSuiteW+.exe" is running. It will be resumed next time you start the tool.

(2) Download and install V3.00.05 of device information file managed by CS+ for the RL78 family of MCUs from the following URL.

https://www.renesas.com/cs+_download

The program will be available from January 20.

3.2 For CubeSuite+ V2.02.01 and Earlier Versions

Please download and install the evaluation edition of CS+ for CC

V3.03.00 or CS+ for CA, CX V3.01.00 (which corresponds to the compiler you are using) from the following URL.

https://www.renesas.com/cs+_download

Then, update your program by using the method in 3.1 (1) or (2) above.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.