

RENESAS TOOL NEWS on May 1, 2006: RSO-E8-060501D

The Emulator Software for the E8 Emulator Revised to V.2.07 Release 01

We have revised the emulator software for the E8 on-chip debugging emulator from V.2.07 Release 00 to V.2.07 Release 01.

1. Descriptions of Revision

Among the emulator debuggers included in the previous E8 emulator software, the H8/300H Tiny, H8/300H Super Low Power, H8/300L Super Low Power E8 emulator debugger has been revised to V.1.02.01. The others have not been revised.

The following problem has been fixed:

When any MCU of the H8/36109F, H8/36077F, or H8/36094F is targeted for debugging, Communication Timeout Error may arise at a break point.

2. How to Update Your Product

Free-of-charge online update is available. If you are using the product concerned, download the executable file of the update program from the download site and execute it.

NOTICES:

1. You can select an update program out of two: the full-package and the debugger package edition. The former contains a full set of the emulator debuggers for the E8 emulator, the High-performance Embedded Workshop, the evaluation version of the C compiler package, the AutoUpdate utility, and the user's manual. Note, if you select the latter, that it contains the emulator debuggers for the E8 emulator and the High-performance Embedded Workshop only.
2. If the update program is installed in the system where the High-performance Embedded Workshop V.4.00.02 or earlier resides, it will be upgraded to V.4.00.03.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.