IDT

Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116   Fax #: (408) 727-2328

Errata Notification

EN #: LEN-02-02   Errata Revision #:   0

Issue Date: April 29, 2002   Effective Date: April 29, 2002

Product Affected: IDT74CBTLV3862

ERRATA DETAILS: **ATTACHMENT**   ■ Yes   ☐ No

■ Data Sheet Errata

☐ Device Errata   Characterization data on IDT74CBTLV3862 OE vs. $\overline{OE}$ disable times

☐ Device Manual Errata   requires two sets of specifications be shown in data sheet.

☐ Application Notes Errata   (Please see the attachment for the detail).

☐ Other (Please Specify)

IDT Web Site Location:

http://www.idt.com/products/pages/Bus_Switches.html

CUSTOMER NOTIFICATION:
As a result of Errata listed above, IDT has decided to notify you through this Errata Notification.
We recommend you to review this notification in details prior to the use of affected product in your application.
Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____   E-Mail Address: _____

Name/Date: _____   Phone #: _____

Title: _____   Fax # : _____

CUSTOMER COMMENTS: _____

Attachment for Errata # LEN-02-02

Switching Characteristics

OLD TABLE

Symbol	Parameter	Vcc = 2.5 +/- 0.2V		Vcc = 3.3V +/- 0.3V	
		Min	Max	Min	Max
Tdis	Output Disable Time $\overline{\overline{OE}}$ or OE to A or B	1ns	5ns	1ns	5ns

NEW TABLE

Symbol	Parameter	Vcc = 2.5 +/- 0.2V		Vcc = 3.3V +/- 0.3V	
		Min	Max	Min	Max
Tdis	Output Disable Time $\overline{OE}$ to Aor B	1ns	5ns	1ns	5ns
Tdis	Output Disable Time OE to Aor B	1ns	5ns	1ns	6ns