RENESAS TECHNICAL UPDATE

Product classification	MPU & MCU	Document No.	TN-V85-A029A/E	Rev.	1.00
Title	Document Modification of Standard Self Programming Flow		Notification classification	Technical Information	

Affected Products	V850E/Dx3 series	Affected production lot	Related documents	User's Manual : Hardware of affected products
		All lots		

In the V850E/Dx3 series User's Manual about a standard self-programming flow of the flash memory, we add a postscript as follows, because there was an omission of description.

1. Notification

We correct from "Disable setting of standby mode other than the HALT mode" to "Disable setting of standby mode".

Standard Self Programming Flow