RENESAS Tool News

Corrections to SH7080 Series, SH-2A E200F Emulator; and SuperH Family E10A-USB Emulator Additional Document for User's Manual, Supplementary Information on Using the SH7206

We notify corrections to the following documents:

- SH7080 Series, SH-2A E200F Emulator Additional Document for User's Manual, Supplementary Information on Using the SH7206
  (Document No. REJ10B0172-0300)
- SuperHTM Family E10A-USB Emulator Additional Document for User's Manual, Supplementary Information on Using the SH7206
  (Document No. REJ10B0154-0200)

---

1. **SH7080 Series, SH-2A E200F Emulator Additional Document for User's Manual, Supplementary Information on Using the SH7206**
   (Document No. REJ10B0172-0300)

1.1	Page 8, next to bottom pin in SH7206, right in Figure 1.2 Delete pin name low-active ASEBRK and the wiring to the pin.
1.2	Page 8, next to top line in Figure 1.2 For All pulled-up at 4.7 kOhm or more read All pulled up through 4.7 kOhm each

The incorrect figure with the above errors located:

The corrected figure:

2. SuperHTM Family E10A-USB Emulator Additional Document for User's Manual, Supplementary Information on Using the SH7206

(Doc. No. REJ10B0154-0200)

2.1	Page 7, next to bottom pin in SH7206, right in Figure 1.3 Delete pin name low-active ASEBRK and the wiring to the pin.
2.2	Page 7, next to top line in Figure 1.3 For All pulled-up at 4.7 kOhm or more read All pulled up through 4.7 kOhm each

The incorrect figure with the above errors located:

The corrected figure:

2.3	Page 9, next to bottom pin in SH7206, right in Figure 1.4 Delete pin name low-active ASEBRK and the wiring to the pin.
2.4	Page 9, next to top line in Figure 1.4 For All pulled-up at 4.7 kOhm or more read All pulled up through 4.7 kOhm each

The incorrect figure with the above errors located:

The corrected figure: