[Notes]

Renesas Flash Programmer

Overview

When using the Renesas Flash Programmer, a software tool for programing flash memory, note the following.

1. Caution regarding an RPI file

1. Caution regarding an RPI file

1.1 Applicable Products

Renesas Flash Programmer V3.08.00

1.2 Applicable Devices

➢ RL78 family (excluding RL78/G10, RL78/G1M, and RL78/G1N)

➢ Power Management (battery management ICs)

➢ Renesas USB Power Delivery family (C30 group)

➢ Motor Driver/Actuator Driver ICs (motor control ICs)

1.3 Details

If you execute the [Program] or [Verify Flash Options] command using an RPI file on which no flash option is set, the command does not end normally and returns the following error:

"Error (E3000108): There is no data in the operation range."

1.4 Schedule for fixing the problem

This problem will be fixed in V3.08.01. This program will be available from January 20, 2021.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jan.16.21	-	First edition issued

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,

Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/