# RENESAS Tool News

## Device Information (Managed by CS+) for RX Family Revised to V1.05.00

We will be revising the device information file (managed by CS+) for the RX family of MCUs and accordingly will change the version number from 1.04.00 to 1.05.00.

---

1. Product and Versions to Be Updated
   (1) Device information file managed by CubeSuite+ for the RX family of
      MCUs (CubeSuite+ DevInfo_RX)
        V1.03.00 or earlier
   (2) Device information file managed by CS+ for the RX family of MCUs
      (CS+ Device Information for RX)
        V1.04.00

   Check your version number of "CubeSuite+ DevInfo_RX" or "CS+ Device
   Information for RX" with reference to the procedure described under the
   heading "Components" at the URL below.
    https://www.renesas.com/cs+_ver

2. Description of Revision
   (1) Addition of Supported MCUs
      The following MCUs will be added to the supported line.
        - RX113 group of MCUs
           R5F51135A, R5F51136A, R5F51137A, R5F51138A

   (2) Correction to Device Information
      The I/O header files for the following MCU groups and the information
      of the registers displayed in each debugger IO panel will be changed.
        - RX210 group
        - RX21A group
        - RX220 group
        - RX621/RX62N group
        - RX62T group
        - RX62G group

- RX64M group

(3) Correction of a Problem Announced in a Cautionary Note
   A problem that we announced in a cautionary note (issue No.
   141001/tn5 of Renesas Tool News) will be fixed.
    - With using of the RX64M group
      For more information on the problem, refer to the URL below.
https://www.renesas.com/search/keyword-search.html#genre=document&q=141001tn5

   For more information on the correction, refer to the URL below (the
   information will be on the page from December 5).
    https://www.renesas.com/cubesuite+/CubeSuitePlus_DevInfo_RX.html

3. Updating Your Product
   Online updating is available free of charge. To update either your
   commercial edition or evaluation edition of CS+, use either of the
   following methods.

3.1 For CS+ V3.00.00 or Later
    To update your program, use either of the following methods:
   (1) On the Start menu, select Programs and then Renesas Electronics CS+
      to start the Update Manager.
      This service will be available from December 5.

      Note: If your CS+ has been launched with rapid startup enabled,
          exit the CS+ once, and then run the Update Manager.
          If the CS+ is resident in the notification area of Windows
          (system tray) due to rapid startup, an error occurs and
          produces the following message:
          ---------------------
          M0120001
          Installation is suspended because "CubeSuite+W.exe" is
          running.
          It will be resumed next time you start the tool.
          ---------------------

   (2) Download and install V1.05.00 of device information file managed by
      CS+ for the RX family of MCUs from the following URL.

        https://www.renesas.com/cs+_download
      The above program will be available from December 5.

3.2 For CubeSuite+ V2.02.01 or Earlier
    Please download and install the evaluation edition of CS+ V3.00.00 from
    the following URL:
     https://www.renesas.com/cs+_download

Then, update your program by using the method in 3.1 (1) or (2) above.

---