End Of Life Notice

Notification – PLC26024
18 September 2026

To: Our Valued Customers

Overview: The purpose of this revision is to add additional part numbers to this notification that were excluded from the original notification.

Affected Products: Attached is a list of products affected by this notification.

Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

Key Dates:

Standard Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	**14-Mar-27**
Last Shipment (LTS)	**14-Sep-27**
Custom/Proprietary Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	**14-Sep-27**
Last Shipment (LTS)	**14-Mar-28**

Response: Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Any order resulting from this notice shall be governed by Renesas's General Terms and Conditions or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Renesas will attempt to honor all such purchase orders and scheduled delivery dates but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please contact your local sales representative with any questions or comments.
Thank you for your attention.

Sincerely,
Renesas Electronics

Exact Renesas Part #	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design Part Number	Reason
CN243-SMRTOXIEVZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
EL7158ISZ-T7A	9/4/2026	3/14/2027	9/14/2027	EL7158ISZ	Market Decline
HS0-565BEH-Q	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS0-565BRH/SAMPLE	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS0-565BRH-Q	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS1-565BEH-Q	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS1-565BRH/PROTO	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS1-565BRH-Q	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS1-565BRH-QS2793	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS9-565BEH-Q	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS9-565BEH-QS2793	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS9-565BRH/PROTO	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS9-565BRH-Q	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS9-565BRH-QR6098	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
HS9-565BRH-QS2793	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL28127MSOPEVAL1Z	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL28127SOICEVAL1Z	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL28634EV2Z	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL3150EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL3150EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL3150EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48316-IPT	Manufacturing Discontinuance
ISL3150EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48316-IPT	Manufacturing Discontinuance
ISL3152EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL3152EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL3152EIBZ-T7	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL3152EIBZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL3152EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
ISL3152EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
ISL3152EIUZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
ISL3153EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
ISL3153EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
ISL3153EIUZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
ISL3155EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL3155EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL3155EIBZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL3156EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL3156EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL3156EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
ISL3156EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
ISL3156EIUZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
ISL3158EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL3158EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL3158EIBZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL3158EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
ISL3158EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
ISL3170EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL3170EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL3170EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48316-IPT	Manufacturing Discontinuance
ISL3170EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48316-IPT	Manufacturing Discontinuance
ISL3172EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL3172EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL3172EIBZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL3172EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
ISL3172EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
ISL3173EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48326-IRT	Manufacturing Discontinuance
ISL3173EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48326-IRT	Manufacturing Discontinuance
ISL3173EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
ISL3173EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
ISL3175EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL3175EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL3175EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
ISL3175EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
ISL3176EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL3176EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL3176EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
ISL3176EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
ISL3176EIUZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
ISL3178EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn	LTS / Obsolete Date	Replacement / Similar / Re-Design Part Number	Reason
ISL3178EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL3178EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
ISL3178EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
ISL32600EFUZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32600EFUZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32600EFUZ-T7A	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32601EFBZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32601EFBZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32601EFBZ-T7A	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32601EFUZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32601EFUZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32601EFUZ-T7A	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32603EFUZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32603EFUZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32603EFUZ-T7A	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32612EFHZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32612EFHZ-T7A	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32614EFHZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL32614EFHZ-T7A	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL4489EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL4489EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL55001IBZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL55001IBZ-T13	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL55001IBZ-T7	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL58360IIZ-EVALZ	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL58410IIZ-EVALZ	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL58510IIZ-EVALZ	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL58511IIZ-EVALZ	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6228EVAL3Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6228HIEVAL3Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6228LOEVAL3Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6236EVAL1	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6236EVAL2	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL62386HIEVAL1Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL62386LOEVAL1Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6261AEVAL1Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6261AEVAL2Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6261EVAL1Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6269AEVAL2Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL62771HRTZ	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL62771HRTZ-T	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL62771IRTZ	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL62771IRTZ-T	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6277AHRZ-T	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6277AHRZ-TS2378	9/4/2026	9/14/2027	3/14/2028	None	Market Decline
ISL6277AIRZ-T	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL6506BCBZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL6558EVAL2Z	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL6558IRZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL6558IRZ-TK	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL81483IBZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL81483IBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL81487EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL81487EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL81487EIPZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL81487IBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL81487IBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL81487LIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL81487LIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL81487LIPZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83070EIBZA	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL83070EIBZA-T	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL83071EIBZA	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83071EIBZA-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83072EIBZA	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL83072EIBZA-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL83072EIBZA-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL83072EIUZA	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn	LTS / Obsolete Date	Replacement / Similar / Re-Design Part Number	Reason
ISL83072EIUZA-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
ISL83075EIBZA	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL83075EIBZA-T	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL83075EIUZA	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
ISL83075EIUZA-T	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
ISL83076EIBZA	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL83076EIBZA-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL83076W	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83077EIBZA	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83077EIBZA-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83078EIBZA	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL83078EIBZA-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL83078EIUZA	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
ISL83078EIUZA-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
ISL83080EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL83080EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL83082EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL83082EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL83082EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
ISL83082EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
ISL83083EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
ISL83083EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
ISL83085EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL83085EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
ISL83085EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
ISL83085EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
ISL83086EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL83086EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL83086EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
ISL83086EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
ISL83088EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL83088EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL83088EIUZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
ISL83088EIUZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
ISL83483IBZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL83483IBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL83483IBZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL83485IBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL83485IBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL83485IBZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL83488IBZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83488IBZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83490IBZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83490IBZ-T	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
ISL83491IBZ	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL83491IBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL83491IBZ-T7A	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL8483EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL8483EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL8485CBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485CBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485EABZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485EABZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485ECBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485ECBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485EIBZ-TR5194	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485IBZ	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8485IBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
ISL8487EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL8487EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
ISL8489EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL8489EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
ISL8491EIBZ	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL8491EIBZ-T	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
ISL88550AEVAL1Z	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL95809W	9/4/2026	3/14/2027	9/14/2027	None	Market Decline

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn	LTS / Obsolete Date	Replacement / Similar / Re-Design Part Number	Reason
ISL95828HRTZS2378	9/4/2026	9/14/2027	3/14/2028	None	Market Decline
ISL95861IRTZ	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
ISL95861IRTZ-T	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
JP167-PLCACREFZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
RAA225000GNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA225000R22GNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA225000R2EGNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA225000R2FGNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA225000R47GNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA225000R7SGNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA225001GNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA225501CR0BGNP#HA0	9/4/2026	9/14/2027	3/14/2028	None	Market Decline
RAA225701CS01GNP#HB0	9/4/2026	9/14/2027	3/14/2028	None	Market Decline
RAA2257034GNP#HB0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA229139GNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA229200GNP#HA0	9/4/2026	3/14/2027	9/14/2027	None	Market Decline
RAA7881502GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
RAA7881502GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
RAA7881502GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48316-IPT	Manufacturing Discontinuance
RAA7881502GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48316-IPT	Manufacturing Discontinuance
RAA7881522GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
RAA7881522GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
RAA7881522GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
RAA7881522GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
RAA7881532GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48326-IRT	Manufacturing Discontinuance
RAA7881532GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48326-IRT	Manufacturing Discontinuance
RAA7881532GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
RAA7881532GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
RAA7881552GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
RAA7881552GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
RAA7881552GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
RAA7881552GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
RAA7881562GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
RAA7881562GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
RAA7881562GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
RAA7881562GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
RAA7881582GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
RAA7881582GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
RAA7881582GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
RAA7881582GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
RAA7881702GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
RAA7881702GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48316-IRT	Manufacturing Discontinuance
RAA7881702GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48316-IPT	Manufacturing Discontinuance
RAA7881702GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48316-IPT	Manufacturing Discontinuance
RAA7881722GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
RAA7881722GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48315-IST	Manufacturing Discontinuance
RAA7881722GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
RAA7881722GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48315-IMT	Manufacturing Discontinuance
RAA7881732GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48326-IRT	Manufacturing Discontinuance
RAA7881732GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48326-IRT	Manufacturing Discontinuance
RAA7881732GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
RAA7881732GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48326-IPT	Manufacturing Discontinuance
RAA7881752GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
RAA7881752GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48325-IST	Manufacturing Discontinuance
RAA7881752GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
RAA7881752GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48325-IMT	Manufacturing Discontinuance
RAA7881762GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
RAA7881762GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48356-IRT	Manufacturing Discontinuance
RAA7881762GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
RAA7881762GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48356-IPT	Manufacturing Discontinuance
RAA7881782GSP#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
RAA7881782GSP#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48355-IST	Manufacturing Discontinuance
RAA7881782GSU#AB0	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
RAA7881782GSU#HB0	9/4/2026	3/14/2027	9/14/2027	RRA48355-IMT	Manufacturing Discontinuance
US069-MOTCTRLEV2Z	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
US157-G2LSBCPOCZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance
US245-DRPAICAMDEMOZ	9/4/2026	3/14/2027	9/14/2027	None	Manufacturing Discontinuance