Change PLP Products List

Change PLP products will be listed Internet site for about three months following the date of the change.

Update :Continuation:254(RA:17,Syncrgy:5,RX:232) **↓(Notice)Duplication 78 P/Ns contains.** Sep. 30, 2024

No	Registration	PLP Status	Product	L1 Layer Name	L2 Layer Name	L3 Layer Name	L4 Layer Name	Part Name	PLP Orderable Part Name (before)	PLP Orderable Part Name (after)	Equivalent or Similar	PLP Termination date (before)	PLP Termination date (after)	Remarks	History	Update
1	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RA_Family	RA4	RA4M1	R7FA4M1AB3CFL	R7FA4M1AB3CFL#AA0	R7FA4M1AB3CFL#BA0			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
2	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RA_Family	RA4	RA4M1	R7FA4M1AB3CFM	R7FA4M1AB3CFM#AA0	R7FA4M1AB3CFM#BA0			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
3	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RA_Family	RA4	RA4M1	R7FA4M1AB3CFP	R7FA4M1AB3CFP#AA0	R7FA4M1AB3CFP#BA0			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
4	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651CDDFB	R5F5651CDDFB#30	R5F5651CDDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
5	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651CDDFM	R5F5651CDDFM#30	R5F5651CDDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
6	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651CDDFP	R5F5651CDDFP#30	R5F5651CDDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
7	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651CHDFB	R5F5651CHDFB#30	R5F5651CHDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
8	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651CHDFM	R5F5651CHDFM#30	R5F5651CHDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
9	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651CHDFP	R5F5651CHDFP#30	R5F5651CHDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
10	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651EDDFB	R5F5651EDDFB#30	R5F5651EDDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
11	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651EDDFM	R5F5651EDDFM#30	R5F5651EDDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
12	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651EDDFP	R5F5651EDDFP#30	R5F5651EDDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
13	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651EHDFB	R5F5651EHDFB#30	R5F5651EHDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
14	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651EHDFM	R5F5651EHDFM#30	R5F5651EHDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
15	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F5651EHDFP	R5F5651EHDFP#30	R5F5651EHDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
16	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F56SNCDDFB	R5F56SNCDDFB#30	R5F56SNCDDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
17	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F56SNCDDFP	R5F56SNCDDFP#30	R5F56SNCDDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
18	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F56SNCHDFB	R5F56SNCHDFB#30	R5F56SNCHDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
19	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F56SNCHDFP	R5F56SNCHDFP#30	R5F56SNCHDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
20	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F56SNEDDFB	R5F56SNEDDFB#30	R5F56SNEDDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
21	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F56SNEDDFP	R5F56SNEDDFP#30	R5F56SNEDDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
22	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F56SNEHDFB	R5F56SNEHDFB#30	R5F56SNEHDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
23	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX63S	R5F56SNEHDFP	R5F56SNEHDFP#30	R5F56SNEHDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
24	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX66T	R5F566TKADFP	R5F566TKADFP#30	R5F566TKADFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
25	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX72T	R5F572TKADFP	R5F572TKADFP#30	R5F572TKADFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
26	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX66T	R5F566TAADFP	R5F566TAADFP#30	R5F566TAADFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
27	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX66T	R5F566TABDFP	R5F566TABDFP#30	R5F566TABDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
28	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX66T	R5F566TEBDFP	R5F566TEBDFP#30	R5F566TEBDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
29	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MFCDFB	R5F571MFCDFB#30	R5F571MFCDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
30	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MFCDFC	R5F571MFCDFC#30	R5F571MFCDFC#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
31	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MFCDFP	R5F571MFCDFP#30	R5F571MFCDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
32	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MFHDFB	R5F571MFHDFB#30	R5F571MFHDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
33	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MFHDFC	R5F571MFHDFC#30	R5F571MFHDFC#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
34	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MFHDFP	R5F571MFHDFP#30	R5F571MFHDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
35	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MGCDFB	R5F571MGCDFB#30	R5F571MGCDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
36	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MGCDFC	R5F571MGCDFC#30	R5F571MGCDFC#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
37	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MGCDFP	R5F571MGCDFP#30	R5F571MGCDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
38	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MGHDFB	R5F571MGHDFB#30	R5F571MGHDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
39	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MGHDFC	R5F571MGHDFC#30	R5F571MGHDFC#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
40	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MGHDFP	R5F571MGHDFP#30	R5F571MGHDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
41	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MJCDFB	R5F571MJCDFB#30	R5F571MJCDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
42	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MJCDFC	R5F571MJCDFC#30	R5F571MJCDFC#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
43	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MJCDFP	R5F571MJCDFP#30	R5F571MJCDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
44	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MHDFB	R5F571MHDFB#30	R5F571MHDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
45	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MHDFC	R5F571MHDFC#30	R5F571MHDFC#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
46	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MHDFP	R5F571MHDFP#30	R5F571MHDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
47	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MLCDFB	R5F571MLCDFB#30	R5F571MLCDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
48	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MLCDFC	R5F571MLCDFC#30	R5F571MLCDFC#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
49	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MLCDFP	R5F571MLCDFP#30	R5F571MLCDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
50	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MLHDFB	R5F571MLHDFB#30	R5F571MLHDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
51	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX71M	R5F571MLHDFC	R5F571MLHDFC#30	R5F571MLHDFC#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
52	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX66N	R5F566NNDDFB	R5F566NNDDFB#30	R5F566NNDDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
53	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX66N	R5F566NNDDFP	R5F566NNDDFP#30	R5F566NNDDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
54	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX72N	R5F572NNDDFB	R5F572NNDDFB#30	R5F572NNDDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
55	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX700	RX72N	R5F572NNDDFP	R5F572NNDDFP#30	R5F572NNDDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
56	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514ADFB	R5F56514ADFB#30	R5F56514ADFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
57	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514ADFP	R5F56514ADFP#30	R5F56514ADFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
58	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514BDFB	R5F56514BDFB#30	R5F56514BDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
59	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514BDFM	R5F56514BDFM#30	R5F56514BDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
60	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514BDFP	R5F56514BDFP#30	R5F56514BDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
61	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514EDFB	R5F56514EDFB#30	R5F56514EDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
62	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514EDFP	R5F56514EDFP#30	R5F56514EDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
63	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514FDFB	R5F56514FDFB#30	R5F56514FDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
64	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514FDFM	R5F56514FDFM#30	R5F56514FDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
65	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56514FDFP	R5F56514FDFP#30	R5F56514FDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
66	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517ADFB	R5F56517ADFB#30	R5F56517ADFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
67	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517ADFP	R5F56517ADFP#30	R5F56517ADFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
68	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517BDFB	R5F56517BDFB#30	R5F56517BDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
69	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517BDFM	R5F56517BDFM#30	R5F56517BDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
70	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517BDFP	R5F56517BDFP#30	R5F56517BDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
71	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517EDFB	R5F56517EDFB#30	R5F56517EDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
72	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517EDFP	R5F56517EDFP#30	R5F56517EDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
73	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517FDFB	R5F56517FDFB#30	R5F56517FDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
74	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517FDFM	R5F56517FDFM#30	R5F56517FDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
75	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56517FDFP	R5F56517FDFP#30	R5F56517FDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
76	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519ADFB	R5F56519ADFB#30	R5F56519ADFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
77	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519ADFP	R5F56519ADFP#30	R5F56519ADFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
78	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519BDFB	R5F56519BDFB#30	R5F56519BDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
79	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519BDFM	R5F56519BDFM#30	R5F56519BDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
80	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519BDFP	R5F56519BDFP#30	R5F56519BDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
81	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519EDFB	R5F56519EDFB#30	R5F56519EDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
82	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519EDFP	R5F56519EDFP#30	R5F56519EDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
83	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519FDFB	R5F56519FDFB#30	R5F56519FDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
84	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519FDFM	R5F56519FDFM#30	R5F56519FDFM#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
85	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F56519FDFP	R5F56519FDFP#30	R5F56519FDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
86	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N4ADFB	R5F565N4ADFB#30	R5F565N4ADFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
87	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N4ADFP	R5F565N4ADFP#30	R5F565N4ADFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
88	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N4BDFB	R5F565N4BDFB#30	R5F565N4BDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
89	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N4BDFP	R5F565N4BDFP#30	R5F565N4BDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
90	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N4EDFB	R5F565N4EDFB#30	R5F565N4EDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
91	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N4EDFP	R5F565N4EDFP#30	R5F565N4EDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
92	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N4FDFB	R5F565N4FDFB#30	R5F565N4FDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
93	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N4FDFP	R5F565N4FDFP#30	R5F565N4FDFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
94	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N7ADFB	R5F565N7ADFB#30	R5F565N7ADFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
95	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N7ADFP	R5F565N7ADFP#30	R5F565N7ADFP#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
96	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX65N, RX65I	R5F565N7BDFB	R5F565N7BDFB#30	R5F565N7BDFB#10			Dec. 2038	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
97	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Micro

200	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637BDDFP	R5F5637BDDFP#V1	R5F5637BDDFP#H0			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
201	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637BEDFP	R5F5637BEDFP#V0	R5F5637BEDFP#H0			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
202	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637CADFA	R5F5637CADFA#V1	R5F5637CADFA#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
203	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637CADFP	R5F5637CADFP#V1	R5F5637CADFP#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
204	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637CDDFA	R5F5637CDDFA#V1	R5F5637CDDFA#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
205	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637CDDFP	R5F5637CDDFP#V1	R5F5637CDDFP#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
206	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637CEDFP	R5F5637CEDFP#V1	R5F5637CEDFP#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
207	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EADFA	R5F5637EADFA#V1	R5F5637EADFA#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
208	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EADFB	R5F5637EADFB#V1	R5F5637EADFB#H1			Mar, 2036	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
209	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EBDFA	R5F5637EBDFA#V1	R5F5637EBDFA#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
210	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EBDFB	R5F5637EBDFB#V1	R5F5637EBDFB#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
211	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EDDFB	R5F5637EDDFB#V1	R5F5637EDDFB#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
212	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EDDFP	R5F5637EDDFP#V1	R5F5637EDDFP#H1			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
213	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EEDFA	R5F5637EEDFA#V0	R5F5637EEDFA#H0			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
214	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EEDFB	R5F5637EEDFB#V0	R5F5637EEDFB#H0			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
215	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63T	R5F5637EEDFP	R5F5637EEDFP#V0	R5F5637EEDFP#H0			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
216	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56104VDFP	R5F56104VDFP#V0	R5F56104VDFP#H0			Mar, 2031	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
217	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56104VNFP	R5F56104VNFP#V0	R5F56104VNFP#H0			Mar, 2031	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
218	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56106VNFP	R5F56106VNFP#V0	R5F56106VNFP#H0			Mar, 2031	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
219	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56106VDBG	R5F56106VDBG#U0	R5F56106VDBG#G0			Mar, 2026	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
220	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56106WNBG	R5F56106WNBG#U0	R5F56106WNBG#G0			Mar, 2026	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
221	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56108VDFP	R5F56108VDFP#V0	R5F56108VDFP#H0			Mar, 2031	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
222	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56108VNFP	R5F56108VNFP#V0	R5F56108VNFP#H0			Mar, 2031	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
223	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56108WDBG	R5F56108WDBG#U0	R5F56108WDBG#G0			Mar, 2026	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
224	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX610	R5F56108WNBG	R5F56108WNBG#U0	R5F56108WNBG#G0			Mar, 2026	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
225	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56316CDBG	R5F56316CDBG#U0	R5F56316CDBG#G0			Dec, 2027	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
226	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56316CDFB	R5F56316CDFB#V0	R5F56316CDFB#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
227	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56316CDFP	R5F56316CDFP#V0	R5F56316CDFP#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
228	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56316DDFB	R5F56316DDFB#V0	R5F56316DDFB#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
229	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56316DDFP	R5F56316DDFP#V0	R5F56316DDFP#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
230	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56316EDFB	R5F56316EDFB#V0	R5F56316EDFB#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
231	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56317CDFB	R5F56317CDFB#V0	R5F56317CDFB#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
232	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56317CDFP	R5F56317CDFP#V0	R5F56317CDFP#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
233	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56317DDFB	R5F56317DDFB#V0	R5F56317DDFB#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
234	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56317DDFP	R5F56317DDFP#V0	R5F56317DDFP#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
235	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56317SDFB	R5F56317SDFB#V0	R5F56317SDFB#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
236	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56318CDBG	R5F56318CDBG#U0	R5F56318CDBG#G0			Dec, 2027	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
237	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56318CDFB	R5F56318CDFB#V0	R5F56318CDFB#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
238	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56318CDFP	R5F56318CDFP#V0	R5F56318CDFP#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
239	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56318DDBG	R5F56318DDBG#U0	R5F56318DDBG#G0			Dec, 2027	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
240	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56318DDFB	R5F56318DDFB#V0	R5F56318DDFB#10			Mar, 2036	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
241	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56318DDFP	R5F56318DDFP#V0	R5F56318DDFP#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
242	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F56318SDFB	R5F56318SDFB#V0	R5F56318SDFB#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
243	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631MCDFL	R5F5631MCDFL#V0	R5F5631MCDFL#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
244	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631MCDFM	R5F5631MCDFM#V0	R5F5631MCDFM#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
245	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631MDDFL	R5F5631MDDFL#V0	R5F5631MDDFL#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
246	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631MDDFM	R5F5631MDDFM#V0	R5F5631MDDFM#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
247	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631NCDFL	R5F5631NCDFL#V0	R5F5631NCDFL#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
248	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631NCDFM	R5F5631NCDFM#V0	R5F5631NCDFM#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
249	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631NDDFL	R5F5631NDDFL#V0	R5F5631NDDFL#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
250	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631NDDFM	R5F5631NDDFM#V0	R5F5631NDDFM#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
251	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631PCDFL	R5F5631PCDFL#V0	R5F5631PCDFL#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
252	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631PCDFM	R5F5631PCDFM#V0	R5F5631PCDFM#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
253	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631PDDFL	R5F5631PDDFL#V0	R5F5631PDDFL#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024
254	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX63N, RX631	R5F5631PDDFM	R5F5631PDDFM#V0	R5F5631PDDFM#10			Dec, 2032	Switch to full carton products	PLP Inspection on Sep , 2024	Sep, 2024